

1. Variance vs standard deviation vs standard error
2. If two answers are possible, read the questions again. Both of them probably wrong.
3. Reliability vs failure, read carefully. R=1-F
4. Dependent vs independent, read carefully

Description	Equation
Cell length calculation for histogram and chi-square test for normality	$Cell\ Length = \frac{Range}{(1+3.322 \times \log(n))}$
Plotting position	$PP = \frac{100(i-0.5)}{n}$
Chi-Square Value	$\chi_{df}^2 = \frac{(O_i - E_i)^2}{E_i}$
Variable Control Chart Limits	$Upper\ Control\ Limit, UCL_x = \bar{X} + 3\sigma_0$ $Lower\ Control\ Limit, LCL_x = \bar{X} - 3\sigma_0$
Trial $\bar{X}, R$ –Control Charts Limits	$Upper\ Control\ Limit, UCL_x = \bar{X} + A_2 \bar{R}$ $Lower\ Control\ Limit, LCL_x = \bar{X} - A_2 \bar{R}$
Trial R, R –Control Charts Limits	$Upper\ Control\ Limit, UCL_R = D_4 \bar{R}$ $Lower\ Control\ Limit, LCL_R = D_3 \bar{R}$
The subscript zero (o) indicate revised values.	
$\sigma_0 = \frac{R_0}{d_2}$	
Revised $\bar{X}, R$ –Control Charts Limits	$Upper\ Control\ Limit, UCL_x = \bar{X}_0 + A\sigma_0$ $Lower\ Control\ Limit, LCL_x = \bar{X}_0 - A\sigma_0$
Revised R, R –Control Charts Limits	$Upper\ Control\ Limit, UCL_R = D_2 \sigma_0$ $Lower\ Control\ Limit, LCL_R = D_1 \sigma_0$
Trial $\bar{X}, s$ –Control Charts Limits	$Upper\ Control\ Limit, UCL_x = \bar{X} + A_3 \bar{s}$ $Lower\ Control\ Limit, LCL_x = \bar{X} - A_3 \bar{s}$
Trial s, s –Control Charts Limits	$Upper\ Control\ Limit, UCL_R = B_4 \bar{s}$ $Lower\ Control\ Limit, LCL_R = B_3 \bar{s}$
The subscript zero (o) indicate revised values.	

	$\sigma_0 = \frac{s_0}{c_4}$
Revised $\bar{X}, s$ –Control Charts Limits	Upper Control Limit, $UCL_{\bar{x}} = \bar{\bar{X}}_0 + A\sigma_0$ Lower Control Limit, $LCL_{\bar{x}} = \bar{\bar{X}}_0 - A\sigma_0$
Revised s, s –Control Charts Limits	Upper Control Limit, $UCL_R = B_6\sigma_0$ Lower Control Limit, $LCL_R = B_5\sigma_0$
Process Capability for Centered Process, C_p	$C_p = \frac{USL - LSL}{6\sigma}$ μ & σ can be estimated (calculated) from the revised chart.
Process Capability for Off-Centered Process, C_{p_k}	$C_{p_k} = \min\{C_{pu}, C_{pl}\}$ $C_{pu} = \frac{USL - \mu}{3\sigma}$ $C_{pl} = \frac{\mu - LSL}{3\sigma}$ μ & σ can be estimated (calculated) from the revised chart.
Process Capability (Commonly known as Process Performance) for out of control process	Use revised sample standard deviation, s , in place of population standard deviation, σ , in the above formulas.
Binomial Distribution	$(n \ x) p^x (1 - p)^{n-x}, \mu = np, \sigma = \sqrt{np(1 - p)}$
	$P_a = (d \leq c) = \sum_{d=0}^c \left(\frac{n!}{d!(n-d)!} \right) p^d (1 - p)^{n-d}$ c=acceptance number, d=defectives or nonconformities,
Poisson Distribution	$\frac{e^{-\lambda} \lambda^x}{x!}, \mu = \lambda, \sigma = \sqrt{\lambda}$
	$P_a = (d \leq c) = \sum_{d=0}^c \frac{(np)^d e^{-np}}{d!}$
Proportion or fraction nonconforming in the sample or subgroup, p	$p = \frac{np}{n}$ n = number in the sample or subgroup

	np = number nonconforming in the sample or subgroup
Sample size formula for attribute, n	$n = n = p(1 - p) \left(\frac{z_{\frac{\alpha}{2}}}{E} \right)^2$
Attribute p-chart Control Limits (Trial)	$\text{Upper Control Limit, } UCL_p = \bar{p} + 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}}$ $\text{Lower Control Limit, } LCL_p = \bar{p} - 3\sqrt{\frac{\bar{p}(1-\bar{p})}{n}}$ $\Sigma \bar{p} = \frac{\Sigma np}{\Sigma n}$
Attribute p-chart Control Limits (Revised)	$\text{Upper Control Limit, } UCL_p = p_o + 3\sqrt{\frac{p_o(1-p_o)}{n}}$ $\text{Lower Control Limit, } LCL_p = p_o - 3\sqrt{\frac{p_o(1-p_o)}{n}}$ After revising, delete the out of control points, $p_o = \frac{\Sigma np - np_d}{\Sigma n - n_d}$
Attribute np-chart Control Limits (Trial)	$\text{Control Limits} = n \pm 3\sqrt{n\bar{p}(1 - \bar{p})}$ $\Sigma \bar{p} = \frac{\Sigma np}{\Sigma n}$
Attribute np-chart Control Limits (Revised)	$\text{Control Limits} = np_o \pm 3\sqrt{np_o(1 - p_o)}$ $p_o = \frac{\Sigma np - np_d}{\Sigma n - n_d}$
*c-chart is similar to np-chart	
**c-chart is used for a large (large ship, car, airplane, entire MNSU, etc.) inspection while the np-chart is used for individual piece inspections (a screw is bad or good, a mango is good or bad)	

Attribute c-chart Control Limits (Trial)	$\text{Control Limits} = \bar{c} \pm 3\sqrt{\bar{c}}$ $\bar{c} = \sum \frac{c}{g}$
Attribute c-chart Control Limits (Revised)	$\text{Control Limits} = c_0 \pm 3\sqrt{c_0}$ $c_0 = \frac{\sum c - c_d}{g - g_d}$
Attribute u-chart Control Limits (Trial)	$\text{Control Limits} = \bar{u} \pm 3\sqrt{\frac{\bar{u}}{n}}$ $u = \frac{c}{n} \qquad \bar{u} = \frac{\sum c}{\sum n}$
Attribute u-chart Control Limits (Revised)	$\text{Control Limits} = u_0 \pm 3\sqrt{\frac{u_0}{n}}$ $u_0 = \frac{\sum c - c_d}{n - n_d}$
Acceptance Sampling, Sample Size Calculation based on the Producer's risk	$n = \frac{nP_{0.95}}{P_{0.95}}$
Acceptance Sampling, Sample Size Calculation based on the Consumer's risk	$n = \frac{nP_{0.10}}{P_{0.10}}$
Average Outgoing Quality	$AOQ = P_a p \left[1 - \frac{n}{N} \right]$
Double Sampling Plan	$P_a = p_0 + (p_1 p_2 + p_1 p_1 + p_1 p_0) + (p_2 p_1 + p_2 p_0)$
Average Sample Number	$ASN = n_1 + n_2 P_2; P_2 = \text{probability of requiring a second sample}$