

CNC Plasma Cutter Manual

CNC Plasma Cutter Manual

Last updated: 29/10/24

Contents

1. Introduction
 2. Personal Protective Equipment (PPE)
 3. Pre-Operation Checklist
 4. Operating Instructions
 5. Post-Operation Procedures
 6. Common Hazards and Mitigation
 7. Maintenance Schedule
 8. Emergency Protocols
 9. Risk Assessment
-

1. Introduction

A CNC plasma cutter is a computer-controlled machine used to cut precise shapes from conductive materials, such as steel, stainless steel, and aluminium. The machine directs a high-temperature plasma arc to melt through the material, while a gas (usually compressed air) blows the molten material away, creating clean cuts. Due to the high voltage, intense heat, and fumes involved, safety protocols are essential for effective and safe operation.

2. Personal Protective Equipment (PPE)

When operating a CNC plasma cutter, the following PPE is required:

- **Welding helmet or face shield (with #9-#12 shade):** Protects eyes from the intense arc and UV radiation.
 - **Flame-resistant gloves:** Protects hands during setup and material handling.
 - **Flame-resistant clothing:** Shields the body from sparks, spatter, and UV exposure.
 - **Respirator or face mask:** Essential when cutting metals that produce fumes, especially in enclosed spaces.
 - **Steel-toe boots with non-slip soles:** Provides foot protection and stability.
-

3. Pre-Operation Checklist

Machine Inspection:

- **Plasma Cutter Condition:** Check the plasma cutter, including cables, torch head, and consumables (nozzles and electrodes) for any signs of wear or damage.
- **Air Compressor Check:** If using compressed air, verify that the air supply is set to the correct pressure and is free of leaks. The air compressor should supply at least 60–80 PSI.
- **Grounding:** Ensure the grounding cable is securely connected to the worktable or directly to the workpiece for a stable circuit.

CNC System Check:

- **Computer and Software:** Confirm that the CNC control software is functioning correctly, and load the desired cutting file (usually in DXF or G-code format).
- **Table Alignment:** Check the alignment of the table and the gantry to ensure precise cuts.
- **Emergency Stop Check:** Confirm that the emergency stop button is functioning properly.

Workspace Preparation:

- **Clear the Area:** Remove any flammable materials from the immediate area.
 - **Ventilation:** Ensure the workspace is well-ventilated or has fume extraction to handle smoke and fumes generated during cutting.
 - **Prepare the Material:** Ensure the workpiece is clean and free of contaminants (e.g., rust, oil, paint) that could interfere with cutting quality.
-

4. Operating Instructions

Setting Up the CNC Plasma Cutter:

1. **Secure the Workpiece:** Place the metal sheet on the cutting table and secure it, ensuring it is flat to prevent movement during cutting.
2. **Attach Ground Clamp:** Connect the ground clamp to the workpiece or table.
3. **Load and Check Cutting Program:** Load the design file in the CNC software, and confirm the settings, including cut speed, power level, and cut path, based on material type and thickness.

Initiating the Cut:

1. **Position the Torch:** Use the CNC controls to position the torch at the starting point of the cut.
2. **Set Cut Parameters:** Double-check the cut parameters, including amperage, speed, and pierce height.
3. **Begin the Job:** Start the cutting operation from the CNC interface, and closely monitor the first few seconds to ensure proper arc initiation and cut quality.

Monitoring the Cutting Process:

- **Observe for Consistency:** Ensure that the plasma arc maintains a steady, even cut along the designated path.
- **Check for Excessive Sparks or Smoke:** Excessive sparks or smoke may indicate a problem with speed, power settings, or air pressure. Pause the operation if adjustments are needed.
- **Avoid Opening the Enclosure (if present):** Keep any protective covers or shields in place during operation to contain sparks and prevent exposure to the arc.

Completing the Cut:

- **Return Torch to Home Position:** After the cut is complete, allow the machine to return the torch head to the home position.
 - **Inspect the Cut:** Carefully examine the edges of the cut for quality, and ensure there is minimal slag or dross.
-

5. Post-Operation Procedures

Cooling and Cleaning:

- **Allow Cooling Time:** Let the workpiece cool down completely before handling to avoid burns.
- **Clean the Cut Area:** Remove any slag or dross from the workpiece using a chisel, grinder, or wire brush if needed.
- **Inspect Consumables:** After use, inspect the nozzle, electrode, and any other consumables for wear, and replace as needed.

Shutdown Procedures:

- **Power Off the CNC Plasma Cutter:** Turn off the plasma cutter, CNC controls, and air supply.
 - **Clean the Work Area:** Remove any leftover material, metal shavings, and debris to prepare for the next use.
 - **Store Cables and Equipment:** Wrap and store cables properly, and ensure the plasma cutter and computer are in a safe, dry area.
-

6. Common Hazards and Mitigation

Electric Shock:

- **Risk:** Plasma cutters operate at high voltages and can cause electric shock.
- **Mitigation:** Ensure that all connections are secure and that the work area is dry. Use insulated gloves when handling connections.

Fire Hazard:

- **Risk:** Sparks and molten metal can ignite nearby flammable materials.
- **Mitigation:** Keep flammable items away from the workspace, and have a fire extinguisher ready.

Fume Inhalation:

- **Risk:** Plasma cutting produces metal fumes that can be harmful if inhaled.
- **Mitigation:** Use adequate ventilation, especially when cutting metals like stainless steel or coated materials. Use a respirator if ventilation is limited.

Eye and Skin Exposure to Arc Flash:

- **Risk:** The plasma arc emits UV and infrared radiation, which can damage eyes and skin.
- **Mitigation:** Wear a welding helmet or face shield with appropriate shading, and keep any enclosures or covers in place.

Noise Exposure:

- **Risk:** CNC plasma cutters can produce high noise levels, especially in prolonged operations.
 - **Mitigation:** Use ear protection if working with the machine for extended periods or in confined spaces.
-

7. Maintenance Schedule

Daily:

- Inspect the torch, nozzle, and electrode for wear, and clean or replace consumables as necessary.
- Check the ground clamp connection for signs of wear or corrosion.

Weekly:

- Inspect and clean the air compressor, ensuring it maintains the correct pressure and airflow.
- Check the CNC gantry and rails for smooth movement, and lubricate moving parts as needed.

Monthly:

- Clean and inspect all hoses and cables for signs of wear, and replace if necessary.
- Test the emergency stop function to ensure it works correctly.

Annually:

- Perform a full calibration of the CNC plasma cutter, including the torch alignment and accuracy of the gantry.

- Replace any heavily used or worn parts, such as rails or gantry bearings.
-

8. Emergency Protocols

1. **In Case of Fire:**
 - Stop the operation immediately, turn off the plasma cutter, and use a CO₂ or ABC fire extinguisher to contain the fire. Evacuate the area if the fire cannot be contained quickly.
 2. **Electric Shock:**
 - Disconnect the power immediately if a shock occurs, and seek medical attention if necessary.
 3. **In Case of Fume Exposure:**
 - Power down the cutter and move to fresh air if symptoms such as dizziness or breathing difficulty occur. Ensure adequate ventilation before resuming work.
 4. **Arc Flash Injury:**
 - Avoid looking directly at the plasma arc without protection. If eye injury occurs, seek medical attention immediately.
-

9. Risk Assessment

Hazard	Who Might Be Harmed	Risk Level	Control Measures	Residual Risk	Additional Actions
Electric Shock	Operator	High	Use dry area, insulated gloves, secure ground	Low	Signage on electrical hazards
Fire	Operator, workspace	High	Clear flammables, keep extinguisher nearby	Low	Fire extinguisher training
Fume Inhalation	Operator	Medium	Use ventilation, wear respirator if needed	Low	Regular fume extraction checks
Arc Flash	Operator, bystanders	High	Use welding helmet, keep enclosure closed	Low	PPE reminders
Burns from Hot Metal	Operator	Medium	Allow cooling before handling	Low	Signage warning of hot surfaces

Noise Exposure	Operator	Medium	Use ear protection	Low	Task rotation if long exposure
----------------	----------	--------	--------------------	-----	--------------------------------

Lone Working Considerations:

Lone operation of a CNC plasma cutter is generally acceptable if:

- The operator is experienced and familiar with the machine's controls and safety procedures.
- A mobile phone or alert system is accessible for emergency contact if necessary.

This manual outlines essential guidelines for the safe and effective operation of a CNC plasma cutter. By following the PPE requirements, setup and handling instructions, and regular maintenance, operators can achieve precise cuts, maintain safety, and extend the machine's lifespan.