

Designing and Milling Custom Circuit Boards for the Roland Monofab SRM-20 with Fusion 360 and FlatCAM

This document is designed to give a short summary showing how to create custom circuit boards using tools widely available at Wheaton College and other fab labs. It is not intended to be a full training manual.

Basic info on what a PCB (printed circuit board) is, and how it works:

<https://learn.sparkfun.com/tutorials/pcb-basics>

<https://www.autodesk.com/products/fusion-360/blog/an-introduction-for-electronics-beginners-printed-circuit-boards-from-10000-feet/>

In this tutorial, we'll make a simple circuit that lights up two LEDs, and connects to a 3.7-volt lithium ion battery. It uses "through-hole" components, which are easy to solder. The raw material for the board is .062" (1.57 mm) thick single-layer copper-coated PC board. It's mostly plastic, with a thin layer of copper on one side that we will cut through to create our traces.



This tutorial does not cover advanced techniques such as double-layer boards, vias, creating custom components, etc.

This is only one of many ways to create a circuit board. For a diagram showing many possible workflows and their strengths and weaknesses, see

https://docs.google.com/drawings/d/1_y4-QAegV5s56sJBFXjrf8ToHd4KgXSRxVFkgnWxnKY/edit

Designing Circuit Schematics with Fusion 360

Autodesk Fusion 360's electronics environment is essentially the industry-standard Autodesk EAGLE, packaged in a Fusion-friendly environment. Helpful links:

Electronics Schematic Walkthrough: <https://www.youtube.com/watch?v=lqwHkB9lsUo>

Sparkfun Using EAGLE: Schematic: <https://learn.sparkfun.com/tutorials/using-eagle-schematic>

Fusion Electronics: Work with a new schematic:

<https://help.autodesk.com/view/fusion360/ENU/?guid=ECD-CREATE-SCHEMATIC>

In this section, we'll lay out a circuit diagram for our board, creating a schematic that shows how things connect without worrying about where they will be located.


To start, in Fusion choose “**New Electronics Design**” from the File menu. Then choose “**New Schematic**” from the toolbar. The toolbar will now look like this:




Use “**Add Part**” to add new parts to the schematic. From the “Tutorial - Fusion 360” library, add one “JSTPH2” battery connector, and two “R-US_AXIAL-7.2MM-PITCH”. Don't worry about where to put them. We also need some through-hole LEDs. Choose two LED_RADIAL from the Optoelectronic library, in your choice of color.

You can **add libraries** to include parts from many outside sources. To add a new library, choose “Open Library Manager” from the Add Parts window, click on the “Available” tab, choose one, and click Use.

Now use the **Move** tool to move the parts into position. The little cross-hair at the center of each component is what you should click on. You can right-click to rotate objects, middle-click to flip, mouse wheel to zoom in and out. You should now have something that looks like the picture at right.



Next, wire up the parts with the **Net** tool. Make sure each wire starts and ends at a “pin” on each part. You want something like this → . You can use the **Delete** tool if you make a mistake.



Important notes for this circuit: make sure Pin 2 on the JST connector (the + side of the battery) is attached to the back of each diode's “arrowhead”, not the arrow tip. It doesn't matter which way the resistors go.

Next, assign values to the resistors with the **Info** tool. Use a resistance of 100 ohms for a red, yellow, or green LED, or 50 ohms for a blue or white one. Of course these are just labels for your convenience, you can put whatever parts into the circuit board you like.

The labels are kind of overlapping each other and ugly. You can either **Move** or **Delete** them by clicking on the crosshair next to the labels (not the one on the part itself).

For complicated boards, it can often be helpful to **Name** individual signal lines. Click on the line coming out of Pin 2 of the battery connector and name it "+3.7V"; click on the line coming out of Pin 1 and name it "GND".

Save your work!

Designing Circuit Boards with Fusion 360

PCB Layout Walkthrough: <https://www.youtube.com/watch?v=VZZBEocoYDA>

Sparkfun Using EAGLE: Board Layout:

<https://learn.sparkfun.com/tutorials/using-eagle-board-layout/all>

Fusion Electronics: Work with a new schematic:

<https://help.autodesk.com/view/fusion360/ENU/?guid=ECD-CREATE-BOARD>


Once you've got a schematic, the next step is to lay out your components physically, and wire them together. Click on "Switch to PCB Document" on the toolbar. You should see a dark grey circuitboard, the footprints of your electronics components, and this toolbar:



Move and **Rotate** the parts into whatever position you like. You can be creative about placement, but you might want to put the battery connector on the edge of the board so it's easy to plug in. Don't **Mirror** the parts, though! Some parts are not mirror symmetric.

I recommend placing your components as close to the bottom left corner of the grey rectangle as possible.

This corner is the X-Y origin, so putting parts here will make the CNC machining step easier later on.



The white lines connecting the components are "airwires". They indicate stuff that has to be connected, but isn't yet.

The next step is to get rid of the airwires, and hook up the parts with real circuit board traces. You can do it manually using **Route Manual**, or you can have Fusion decide where the wires should go by choosing **QuickRoute**. The automated method usually works, but it isn't always pretty. And it's a lot of fun to solve the logic puzzle of which wire should go where so that the wires don't crash into each other. So give manual routing a shot!

If you need more precise control over position, hold down the **Alt** key. If you make a mistake, use **Ripup** to remove a trace and start over. You may also want to use wider traces than the default, so they won't break as easily. I'd choose "**Trace Width**": 20 (.020 inches), unless you have very tiny parts to hook up.

You can add "silkscreen" cosmetic text to your board. This won't be visible if you make the board yourself using the CNC, but it will show up if you have your board made by an outside company. Choose "Document" from the tool tab, set the Layer to "25 tNames", and choose drawing tools or text from the Draw dropdown.




When you're done, you might have something like this: → I added some extra squiggles to the traces just for a visual effect: the circuit will work no matter how they're shaped.

Finally, set the shape and size of the circuit board itself. You can change the size of the dark gray rectangle with the **Move** tool, or delete it and draw your own board shape using the **Board Shape** tools. I made one with curved edges just to show you what's possible.

You can now get a 3D view of what your finished board will look like by choosing **View 3D PCB** from the toolbar. You can insert this the board as a component into any other Fusion 360 design (an instrument panel, or a robot, or whatever.)

You can also go the other way: if you want to make a board that fits into an existing 3D design, choose any sketch in your design and choose **Derive PCB From Sketch** from the File menu, then **Push to 2D PCB**. The best thing about this feature is that if your 3D design changes, your circuit board can change automatically!

Save your 2D and 3D board files now.



Handy Tiny Dimension Conversion Table

<u>Fractional inch</u>	<u>Decimal inch</u>	<u>mils</u>	<u>mm</u>	<u>Typical uses</u>
1/64	.016	16	0.40	Tiny endmill
1/32	.031	31	0.79	Less tiny endmill
1/16	.062	62	1.57	Board cutouts, common board thickness
1/20	.05	50	1.27	Common surface-mount pin spacing
1/10	.1	100	2.54	Common through-hole pin spacing

Creating Gerbers and Drill Files

The standard file format for PCB designs is a “Gerber” file (.gbr). The file format for holes drilled in the PCB is an “Excellon” file (.xln). These are both brand names of early automated PCB-manufacturing machines.

But before we can create them, we need to first make sure your board is manufacturable. If your traces and parts are too small or close together, there could be a problem! Choose “**Rules DRC/ERC**”, then choose “**DRC** ”. You can change the rules, or load in a set of rules provided by a boardmaker. If you’re cutting your own board using a CNC, you should change the settings on the “Clearance” tab to 16 mil (.016 inch) for all options. This corresponds to 1/64 inch, which is the smallest cutting bit we have at Wheaton.

Then choose “**Check**”. If no window pops up, you’re good to go! Otherwise, Fusion will show you which parts of your design are not manufacturable and must be adjusted.

Now, choose the “**Manufacturing**” tab and choose “**CAM Processor**”. Select “**Units: Metric**” and “**Process Job**”. A folder will be created with all the files needed for manufacturing. Congratulations! You have a board design. You can now either send it for outside manufacturing (see the last section) or make it yourself on a CNC (continue below).

Creating CNC files with FlatCAM


Unfortunately you cannot turn your Gerber files into CNC mill operations within Fusion. There are many tools to help you do this: I like FlatCAM (<http://flatcam.org/>), an open-source tool written in Python. It’s easily installed for PC or Linux, and it *will* run on a Mac, but installation on Mac is a pain in the butt.

Step 0: Metric Units

I've had trouble getting drill holes to work properly when working in inches. Click the **Options** tab and choose **Units: mm**.

Step 1: Create isolation geometry from Gerber

Your first step is to find the ZIP file that Fusion created for you and **unzip** it. Then, **fire up FlatCAM**. From File, choose "**Open Gerber...**". You want to load "**GerberFiles/copper_top.gbr**".



We can see the copper traces we planned out in Fusion. Now, we want to make our CNC mill trace along the outside edges to "isolate" these traces from the rest of copper on the surface of the board. Double-click on copper_top.gbr. Set the "**Tool dia:**" to the cutting tool diameter, in mm, you intend to use (for instance, 1/64 inch = 0.4 mm).


Optionally, you can clear away extra copper by making multiple parallel passes with the cutting tool. This will take more time, but might make soldering easier. To do so, set "Width (# of passes)" to 2 or more, and check "Combine Passes".

Another handy option is "**Offset**", at the bottom of the list, which will shift your entire design. You usually want it close to (0,0).

Now choose **Generate Geometry**. A red outline will surround your traces. Click on the "Project" tab: you should see a new entry, "copper_top.gbr_iso".

Step 2: Create CNC path from isolation geometry

Next, we will create the CNC commands to do this work. Double-click on **copper_top.gbr_iso** in the Project tab. For "**Cut Z**" I recommend -0.1 mm to make sure you cut all the way through the copper layer. **Travel Z** is the height of the bit above the surface when not cutting, and should be at least 1 mm. **Feed rate** 75 mm/minute works well, go faster at your own risk. Make sure to set the **Tool dia:** to match your tool! You can probably leave Spindle Speed blank. Then choose Generate. Your tool path will be outlined in blue.




If you make a mistake, you can click on entries in the Project tab, and choose “Delete” and re-do them.

Step 3: Create Gcode from CNC path

Now, go back to the Project tab and double-click on “copper_top_gbr_iso_cnc”. Make sure the tool diameter is right, and then Export G-Code. Name your file something like **traces.nc**.

This G-Code file can be used on any CNC machine. You can also preview it using <https://ncviewer.com/>



Step 4: Create Drill Holes

If your design has through-hole components, you need to drill the holes. Choose “**File/Open Excellon...**” and choose the “**DrillFiles/drill_1_16.xln**” file. You have two options: if you have the right size drill bits, you can *drill* the holes, otherwise you can *mill* them to the right size with an endmill. The endmill must be *narrower than the hole, but longer than the thickness of the PCB*.


Either way, double-click on the drill file in the Project tab. Note the table showing the hole diameters, in mm, in your project.

To **drill** the holes, go to the **Generate CNC Job** section, set “Cut Z” to the thickness of the PCB board (often 1.57 mm), “Travel Z” to 1 mm, feed rate to 75 mm/min, select each hole diameter in

turn, and click **Generate Code**. Then go back to Project and **Export G-Code** for each hole size.

To **mill** the holes, enter your tool size, select all the holes sizes, and click “Generate Geometry” in the Mill Holes section. Then to go back to the project tab and **Generate CNC Job** for each hole size, using the same cutting settings (Cut Z = PCB thickness, Travel Z = 1 mm, feed rate 75 mm/min).

Either way, you should now have one or more CNC objects. Go back to Project and **Export G-Code** for them. Call the files “**drills.nc**” or similar.




Step 5: Create Cutout

Finally, we want to cut the finished circuit out of the PCB stock. You want a big sturdy endmill for this job: 1/16” (1.57 mm) might be good. There are two ways to do this: using FlatCAM’s automated cutout feature, or using your own custom board shape. FlatCAM’s way is easier and gives you “tabs” to keep your board from breaking free, but can only do rectangular shapes.

To use FlatCAM’s automated cutout, double-click on your original coper_top.gbr Gerber file in Projects, then in the **Board Cutout** section, and choose a Tool diameter. Set “Gap Size” to 3 mm. **Generate** the geometry to create a “copper_top.gbr_cutout”.

To use the board shape you designed in Fusion, choose **File / Open Gerber...**, load the “profile.gbr” file, and double-click it. Choose a Tool diameter. Then **Generate Geometry**. Unfortunately, FlatCAM will assume the profile.gbr describes a circuit trace, and will mill on both sides of it. To get rid of the interior cut line, click on the command line on the very bottom of the window and type “**exteriors profile.gbr_iso**”. You should end up with a profile.gbr_iso_exteriors in your Project tab.

Whichever method you used, it's now time to create the CNC job. Double-click either `profile.gbr_iso_exteriors` or `copper_top.gbr_cutout` in the Project tab, and set the "Cut Z" to the full thickness of the board (often 1.6 mm), Travel Z to 1, Feed Rate to 75, pick your tool diameter. I recommend using the "Multi-Depth" option to cut through the board in passes of 0.5 mm depth each. **Generate** the CNC file, then **Export G-Code** as you did in earlier steps. Call this file `cutout.nc`.



You should now have (at least) two `.nc` files: one for the traces and one for the outer profile, plus one or more for any drill holes in your board.

Roland Monofab Operation

Time to fire up the mill and get cutting! But first, an important safety concept:

Air-Cut First for Safety!

You never know what's going to happen the first time you run a CNC job. A bad CNC job will tell the mill to eat itself, and many machines are happy to do so. It's always safest to do an "air cut" first, where you set the Z-axis deliberately too high, so the machine cuts through the air above your board, rather than cutting anything real. Once you know it's working, lower the bit and do a real cut. This tutorial doesn't walk you through the "air cut" process.

Anyway, let's get started on a real cut. The **power button** is on the top back right corner. To operate it, you need to start **VPanel** on the connected PC.



Step 0: VPanel Setup

Click the “**Setup**” button in VPanel. For Command Set, choose **NC Code**¹. For Units, choose “mm”.

Step 1: Material Prep

Use double-stick tape to stick your PC board material to the wooden spoilboard in the Roland. **Make sure there’s double-stick tape under the area where the board will be cut out, if you created a custom board cutout (Option 2 of Step 5 above.)** If not, the board will break loose and fly away.

Step 2: Tool Prep

Use the allen wrench to loosen the set screw on the Roland’s collet (the part that holds the cutting tool.) **Insert your new tool fully, and tighten the set screw.** Now, use the arrow keys in VPanel to **move the bit close** to (but not quite touching) the board material, **loosen the set screw** so the bit falls onto the board, and **re-tighten**. Now we know the bit is just touching the material. (But don’t forget to air-cut first!)

Step 3: Set the Origin Point

Hit the “Z” button in the top right corner of VPanel to **zero the Z work coordinate** at the top of the board material. Now raise the bit in Z, for safety.

¹Always check this setting! users who use MODS to run the Roland mill will switch it to “RML-1 Code”.

Move the bit to the position you want to use as X=0, Y=0. This can be anywhere, but refer to the graphics in FlatCAM to see where your circuit board will be cut relative respect to (0,0)! Hit the “XY” button in the top right corner of VPanel to **zero the Y and Z work coordinates**.

Step 4: Run the Job!

Hit the **Cut** button, and choose the .nc files you want to cut. You can do more than one at a time, so long as they use the same tool size.

Step 5: While Cutting

While the machine is in operation, you can **open the front cover** to make it stop instantly, or hit the **pause** button in VPanel to pause temporarily. In VPanel you can adjust the travel speed (**cutting speed**), or the rotation speed (**spindle speed**). In general, if it’s vibrating and making scary noises, slow down the cutting speed. If the edges are charring while working with large diameter tools, slow down the spindle speed -- otherwise faster is better.

Outside Manufacturing

The Roland CNC can create boards that are functional, but they will be difficult to solder to, they can’t be very complex, and they won’t be pretty. A somewhat less DIY approach is to send your manufacturing files to an online circuit board fabricator. Many of these are big-time factories, but there are some services that will make just a few small boards for makers and hobbyists. Usually they group your order with other peoples’ stuff, so the process takes a bit longer but there’s no minimum order size.

The price is cheap (\$5 per square inch for three copies), and it’s pretty fast (delivery in under two weeks). You can pay more for faster service. In exchange for your time and money, you can easily make double-sided boards with vias (pass-throughs), that make wiring complex circuits easy. You get a solder mask, which looks nicer and keeps solder from going where it’s not supposed to go. You get gold-plated contacts, which won’t corrode over time. And you get a silkscreen, so you can put custom lettering or art on the board.

I really like <https://oshpark.com/>, partly because their solder masks are purple by default. To use their service, when you get to “Creating Gerbers and Drill Files” above, choose “Export CAM” in Fusion rather than “CAM Processor”. Your files will be packaged in a ZIP file that you can upload to OSH Park. From there, everything happens automatically.

