The commander of the guard ship is Captain 1st rank Kuprin Anton Valeryenich.

Appointed by Order of the Minister of Defense of the Russian Federation No. -521 dated

June 09, 2020.

The ship has been in the company since 15.08.2000, introduced by the order of the Commander of the Black Sea Fleet No. 0151 of 29.09.2000.

It was introduced into the first - line ships from 01.10.2021 by order of the commander of the 11th brigade of anti - submarine ships No. 0102 of 28.09.2021.

In the period from December 01, 2021 to January 25, 2022, the course task K-1 was worked out. Special tasks were received from combat units as indicated below:

SHI-1 - 12.01.2022 Rating "satisfactory" PA-1 HTC. ISHOW

-15.01.2022 Rating "satisfactory" MT-1 - mophics is now

11.01.2022 Assessment "worked out" SV-1

- 11.01.2022 Assessment "worked out"

14.01.2022 Assessment "worked out" SHS-1

- 09.01.2022 Assessment "worked out" M-1
- 08.01.2022 Assessment "worked out"

The SS-1 special task has not been accepted from the supply service, due to lack of accuracy, Documentation has been developed, but it is not needed, classes with a personal staff in the specialty and general training are formally conducted, notes and notebooks are absent. The establishments were not prepared, dirty, not well maintained. The organization of special duty has not been worked out. The re-scheduled deadline for completing the task (January 31, 2022) did not give a positive result. The next deadline for completing the SS-1 task has been set for February 10, 2022.

In the period from January 23, 2022 to February 20, 2022, the elements of the K-2 course task were worked out, while preparatory combat exercises were performed AS - 3,7,9,60,50, RS - 59,8, EW - 2,4, GR - 1-4, GB-1 with the assessment successfully, the ship and sea preparation measures have been completed, with the exception of RPU-1.

I. Staffing of personnel: mocro, anymoro cocrana:

ii otannig or perocimen									
	Ofinerspa	Oldies	STIMBLE .	Petty Officers S	ailors pryzynu	Sailors	Total		
Bystate	50	10	11		363		514		
According to the	95.53 V	68	42	34	98	2.8	543		
list Because of	113	99		3	13	2	30		
Vacation	/ / 1	5		3	10		19		
Com-ka		2		1	5		8		
Gospit	2	1		1		1	4		
Pacxon	33	8		5	15		32		
On the face	50	60	42	29	83	247	511		
Prikom.	11	1		1		10	23		
	61	61	42	30	83	257	534		
%	106	67	42	9)	27	69	104		

II. Condition of the hull, emergency, tow, www. for scupulars.

anchor and mooring devices **** Verponers

Nº.	Controlled up sessue	Pemodicity	Date and result of the	Дата
11/11	elements	of the pro-	last check (no.,	date of the III cil
	elements.	verka	kata yakta)	last check.







1.5	Diving inspection of the comus, rudder, screwtop, GAS fairing, outboard openings (dock inspection).	1 time p half a year	23.01.22 g .	23.06.22 g .
2.	Anchor, tow and mooring appear- device.	1 time per year	№-12 26.12.21.	27.12.22 g .

III. Monitoring the state of physical fields KHX HO. HE

Russian

Ne n/n	Controlled fields and devices. Frequer	cy of verification	Date and re- last pro-sockeye salmon	Date of the next pro- perk
1. Acc	oustic field (noise). Note (шумность).	I every 3 years	25.02.20 g . normal	24.02.22
2.	The level of interference in the operation of the gas-	every 3 months	28.12.21 g.	25.03.22
3.	Magnetic field	1 time in 5 months	29.09.21 g . normal	25.03.22
4.	Electric field. we none.	every 10 months	02.04.21 and the norm	03.03.22
5.	Low-frequency electromagnetic field.	developm ent of Zgoda	of 23.02.20 normal	25.03.22
6.	Девиация магнитного компаса.	once a year	13.05.20	11.05.22 g
7.	Скорость корабля и поправки дага.	1 раз в год	14.05.20	.14.05.22 g
8.	Reconciliation of the NRLS	once a year once	11.05.20	.13.05.22 g
9.	MEC.	1 раз в 3 мес.	21.12.20	.26.03.22 g.

IV. Availability and condition of life-saving equipment and boats *** Peace ***

Nt n/n	The beginning of the middle.	to the report card and the supply	And there Provided by the human	The term of	Condition
1. II	P-6/1DA	155/155	155/155	20.10.21	lspr.
2.	Life jackets. CHACHTE, HAINAG.	640	640	18.02.2126	Isprup.
3.	ПСН	(PSN-20) 26 F (PSN-10) 15 P	PSN-20/480 19.03 SN-10/140	3.21 15 19.03.21	lspr. p
4.	Project 21960 boat	1.	1/12	01.06.21	lspr. p.
	RBC	1	50	01.06.21	lspr.
	YAL-6	1	19	01.06.21	Ispr.
7. Std	orm rails would neeps	8	88	27.02 21	lspr.
8. BL-	-680 (rigid sailing)	1.	1/9	01.06.21	lspr.
		Stationary and porta	ble means:	TRAC	
9. Fi	re fighting	22/350	22/350	January 2022	lspr. p.
10.	To combat water	26/160	26/160	January 2022	Ispr. p.
11. A	narium radios-	2	2/3	april 2021	Ispr. p.
12. IE	D'BY	6	6	April 2021	Ispr. p



Russian



English

T

V. Ship Stocks: sopa6.19 Weapon:

	поцр																				
		Rocket					Artil	Artillery Torpedo Topucanoe				oe	ploro								
		пк	P		ZUR	9M	-33 :	zUR 5	B-5	5	130 MM	30 MM	Crp					4	PIB		
Newto	Наименование	Количество	Дата посружи	нита вытружн	Количество	Дата погрузки	дата выпрузки	30,181	Дата погрузки	имента выпрутки	Количество	Количество	Каличество	O print	Количество	Дата посружи	mont squares areas.	Количество	Количество	Ho, spannon E3	Гральное оружие Средства ЭБ
1	БК	16			38			64			540	32400 1	5000						107+		
	113				÷			•				2600 8	3000						J up		. 3
	Vite falo- trepc iii.		19,04,2021	19.04.2022		26.03.2021	26.03.2022		19.04.2021	19,04,2023				10 COT-65		28,03,2021	30,12,2022			-1 комплект (0

Ship stocks

Ne m/m	Changing stocks same on	measurement.	on porma.	If fact. тически.	Notes.
1	Дизельное топлино.		[860]	1370	
2	Oil With 10 CTT	100	1600	15089	
3	TP-46 oil. III-46.	KF	1500	15944	
4	Diesel oil M1432	T	0.2		
5	Water:				
	-boiler room	T	40	29	
	-HIRTIGRAN	T	240	150	
6	Продовольствие:	s/a	30	35	
	*dried	day	30	35	
	fresh:	day	21	26	
7.1	Aviation equipment.	T	24	24	

Availability of devices for receiving (transmitting) fuel, conventional and discharge cargoes pysion

Fork (type) devices	Technical capabilities of the HF.	The next term 1998
Cargo Boom (Crane KE40TM)	81	examination is
Fuel prismnik	120 g/h	01.02.23.01.02.23

VI. State of armament and military equipment sociation Textures

-the condition of weapons and military equipment is set sopure makes:
satisfactory; -the staffing of weapons and military equipment with means a substantial military equipment is substantial military equipment is substantial military equipment is substantial military equipment with mil

VII. Condition of the material part of the ship sopa6.18

-Restrictions and combat use:







- OD No. 4, OP No. 2 restriction on use in modes above 0.6N (order of the Commander of the Black Sea Fleet No. 433 dated 12.04.2020). ...
- the pacifier of the pitching UK-134 (order of the Commander of the Black Sea Fleet No. 1313 dated 24.09.2020);
- passenger elevator (order of the Commander of the Black Sea Fleet No. 1313 dated 09/24/2020);
- the system of remote control of the general court and chemical ventilation reckon Ben-"Ladoga-64" (order of the Commander of the Black Sea Federal Law No. 1313 dated 313 am 09/24/2020);
- the system of automatic control and alarm of the fire, tidal and option of the ballast systems "Caspian-64" (order of the Commander of the Black Sea
- level alarm system in fuel tanks (order of the Commander of the Black Sea Fleet No. 13i3 dated 09/24/2020);
- air system of medium pressure VSD with pneumatic actuators (remote manuscription control of shut-off valves of ship-wide systems) (order of the Commander of the Black Sea Fleet No. 1313 of 09/24/2020);
- a device for transferring cargo on the move "String-M" (order of the Commander of the Black Sea Fleet No. 1313 of 24.09.2020);
- the main mode of MPP-3 (order of the Commander of the Black Sea Fleetomoss No. 788 dated 21.06.2020).
- 3 channels of MT-45 are faulty. A restriction on the combat use of the MT-45 was introduced a MT-45 by Order of the KChF No. 1395 DSP dated 10.10.2020.
- MRO-500 complex (order of the Commander of the Black Sea Fleet No. 1018 dated 06.07.2021)

Ship-wide is sues: Have Bourpock!

I. The deadline for checking the KIP was released - December 23, 2021. According to the instructions of the Deputy

Commander of the Black Sea Fleet for MTO (TLG No. 51 dated 06.01.22) and the decision of the ship commission, the

deadline was extended until 31.03.22.

Navigator combat unit:

- 1. NTSVK Strelva-U Limited in the use of NTSVK Strelna-U in the automatic mode of correction of corrections of the coordinates of the location and course of the ship in connection with the continuation of modernization work.
- 2. AEOP "Sulak" is characterized in the use of AEOP "Sulak" and automatic and semi-automatic modes of measuring the horizontal coordinates of celestial bodies and beret luminous orifices due to the non-availability of a photoelectric combined tube amplifier and the inability to repair or replace it with a similar one.
- 3. AP "Malachite" No. -2 (at the GKP) has been dismantled, is on board, prepared for delivery to the BS BS. The built-in car builder installed in the replacement has not been put into point to operation, has not been commissioned, (due to the solution of extraterrestrial tasks at sea produced). A letter of guarantee was received to the commander of the cruiser from the director of the YURTC "780 RZ TSK", the letter is coordinated with the head of the GS Black Sea Fleet. The letter states that the work under the state contract No. P/1/5/167/ GC-22- DGOZ from 02/28/2020 were completed in full except for the programming of the devices: VAC-IM, pr.2, pr. UI-01, which will be completed with the return of the cruiser to Sevastopol.





4. GSHV January 26, 2022 expired verification period. An application has been prepared for the delivery of the GSHV data that the control of t

Rocket and artillery combat unit: Charles the Charles

- 1. UMZRK "Fort" when checking an electronic shot after capturing a target, there is no binding of missiles to the target, the scoreboard on the FI231K device does not light up, there is no scan on the situation indicator when the receiving and transmitting channel No. 1 is working, the FE21F device is not working properly. A malfunction of the fuses of the protection element lights up, the operation of the CVM No. 1,2 device is not stable, the FC test mode does not pepass, the channel 1 malfunction is lit on the FV27F device, when the scan on the FI234K unit is distorted. It is necessary to involve representatives of JSC "Ratep" in the city of Ser-r. Cep-Pukhov.
- 2. MCRC "Corvette" misalignment of the antenna post by bearing, the angle of the seat by 10°, the device 1 K04 is not working properly, the onboard pitching amplifier 1K1107 is not working, the unit 1K01.07 of the starboard antenna post is not working properly, the operation in the critical mode IK01.07 of the left side antenna post is not working, the detector currents are underestimated. It is necessary to replace the IK01.07 blocks in the amount of 04 pieces. It is necessary to attract representatives of JSC 'Radar-service's BLC.
- 3. ZRK "Osa-MA" No. el antenna post there is no high radiation of the SOC. It is Hootxonecessary to involve representatives of 1127 RZRAV AB
- 4. ZRK "Osa-MA" No. 2 requires FC-1 settings, there is no blocking of the antenna of OH. the SOC. permanent signal of the simulated target on the range indicator, it is necessary to attract representatives of 1127 rZrAV3PAB
- 5. PC-2 of the left side there is no horizontal guidance, the guides are not they come to the starting position, the SB-143-4 spark gap is not working properly 143-4
- 6. PC-2 starboard there is no vertical guidance, the left turnstile does consider a puncture not turn into an electric one. It is necessary to involve representatives of 1127 management 1127
- 7. AK-130 the hydraulic motor of a large pumping station is not working properly, the working fluid is leaking from the drive of the receiver of the left automatic, the working fluid of a small pumping station is leaking from a high-pressure tube, the device 105D is not stable. It is necessary to attract representatives of JSC "Arsen al" St. Petersburg
- 8. AK-630 No. I the control unit is not working properly, there is no voltage of 27 volts, the replacement of the Ao-18 No. 3 machine gun is required due to the limit value of the barrel. It is necessary to attract representatives of 1127 RZRAV 312AB
- 9. CRO "Basalt" the 4C device is not working properly, it is necessary to involve excessive representatives of the NGO "Mashino strosnie". It is necessary to replace 02 ZM-70 products due to the expiration of the period of stay on the ship.

Mine-torn slaughterhouse:

1. Unstable operation of the hydraulic control system of the KMP60-2KM karst No. 1. Adjustment is required with the involvement of representatives of the n/a 27090A

Combat communications unit: # ###

I). Problematic issues:

When the MR-800 radar is operating on radiation (Channel 3), the control of the antenna posts of the R-794-1 satellite communication station disappears and, as a result, the satellite communication channel becomes unstable and can lead to the failure of the station.







operations. A telegram was sent to the manufacturer about the emerging problem in the operation of the satellite communication station.

- 2). Satellite communication station R-794-1:-
- antenna posts No. 1,2 the formation of backlash,
- -curvature of the shafts of the gear motors of the antenna OP drives,
- antenna post No. 1 attenuation of signal reception from the
- spacecraft, failure of the power adapter of the oscilloscope.

The station requires repair by the manufacturer FSUE "Vigetar" cas @FVII «Burctup» (Moscow).

- 3). Faulty communication equipment requiring repair by FSUE "771 RZSS Black Sea Fleet" of the Ministry of Defense of the Russian Federation (Sevastopol):
 - 1. RPU Katran-KB there is no auditory reception in TLG mode. 12 TLL
- 2. UD-M211 (from the battery 83t60k) the adjustment of the printhead is knocked down, it tobket, is impossible to print out the document NCHTA.
- 3. UD-M211 (from the composition of SHAS T-609) the adjustment of the print head is knocked down, it is impossible to print the document.
 - 4. RPDU R-631 No. 2 unit No. 4 in the exciter VMK-KV is not working properly.
 - 5. RPDU R-631 No. 3 does not commute into the path with the AX Cabin-2K.
 - 6. RPDU R-631 No.6 unit No. 5 in the exciter VMK-KV is not working properly. B.
 - 7. RPU R-680 when recoil into the distance, the nominal frequency does not change.
 - 8. RPU R-683 does not go to the reception (constant hissing).
- 9. TLG apparatus P-116 the perforator, the transmitter, the printing press is not working properly.
- 10. R/st R-625 when the radio station is turned on, unit No. 5 emits a hum, unit No. 2 we does not interact with other units of the radio station.

Electromechanical warhead:

- 1. Gas turbine generator GTG-1500-2 No. 1-has worked out the resource before the bulkhead after 5000 Hours of operation (has an operating time of 6362 hours). The operating time has been extended by 500 H Has 500 hours on the instructions of the Deputy Commander of the Black Sea Fleet for MTO (TLG No. 49 of 06.01.22 01.22 d.);
- 2. Gas turbine generator GTG-1250-2 No. 2 head.No. 1548809-worked out the resource before the restart after 2500 hours of operation (has an operating time of 3140 hours). The operating time has been extended by 500 hours on the instructions of the Deputy Commander of the Black Sea Fleet for MTO (TLG No. 49 of 03.01.22).
- 3. Gas turbine generator GTG-1500-1 No. 5 head No. 1477801-uncharacteristic noise in the reactor when idling (no visible defects were detected, the resource was exhausted before decommissioning) (has an operating time of 28191 hours). A restriction on use is imposed only in emergency cases on the instructions of the Deputy Commander of the Black Sea Fleet for MTO (TLG No. 49 of 06.01.22).;
- 4. Gas turbine generator GTG-1250-1 No. 6 head No. 1548809-worked out the resource before the match (has an operating time of 28372 hours). Restrictions have been imposed on the use only in emergency cases on the instructions of the Deputy Commander of the Black Sea Fleet for MTO (TLG No. 46 of 05.01.22).





- 2. MVU-210A the first line of CVM is faulty, device No. 181 is not entered into the system, the device of the UPV (passive magnitude conversion device) is faulty, the BPS-1 Olsht unit is faulty. It is necessary to repair the unit, device No. 175 is not exchanged with ship systems. (the unit BO 01sht is faulty. It is necessary to repair the unit).
- 3. MR-184 in the SDTS mode, on the ICOC screen and the indicator of the KU-D devices. No. 3,6 block U2-3, there is no mark from the peli, unauthorized reset of the "high" voltage of the OD (main diazinone) of the device No. 2,0D (main diazone) of the 2nd channel, the current of the magnetron is maximum 3-4 µA, instead of 25-27 mkA, device No. 6 block of BN and C the light bulb "GAG ON" does not light, the signal from the GAG "Nadir" does not pass, device No. 3 height error when checking in the simulator of the set height, device No. 3 ICOC unit there is no D-3 range sight, device No. 3 dynamic errors are not corresponds to the technical conditions of the product, device No. 3 on the blo -ku-D short-term disappearance of the mark from the target.
 - 4. MP-123 No. 1 (nose) there is no focusing of the TV in the device No. 3. No. 1.
- 5. MP-123 No.2 (port side) unauthorized high voltage reset when BMCOKOTO HARDSWELLER switching from "manual" mode to ipoisk mode, it possess allowed to provide the possess of the posse
- 6. MP-123 No. 3 (starboard side) there is no image on the TV, the width of the beams in the "zahnat" and "antomat" modes do not correspond to THAT, There is no indication of the "SCANNER ON" control lamp on the CAP panel of the device No. 3. (There is no beam scanning), the device No.1 does not rest on the comer of the seat,
- - 8. MG-7 No. 1 (nose) Device No. 1 cable is faulty (cable short circuit).
 - 9. MG-7 No. 2 (feed) device No. 1 is not allowed.
- 10.PSA "Third" device 14 there is no voltage 110V 427 Hz, device 105 there is no voltage 220V 427 Hz, ZIF 121 (pr/b) vertical misalignment by 50 etc., ZIF 121 (l.b) horizontal misalignment by 300 etc., device 14 does not pass the firing circuit, the lamp "Readiness" does not light up launchers", the device 105 does not output the ship's course data to the device 14, the device 105 is not working properly built-in oscilloscope.
- 11.MP-150,152 there is no indication of the radiated power of the transmitter, the CRT control of the transmitting and receiving signal of the II letter is faulty in block B10-1I, the device P4SH (pr/b) there is no "high" voltage, the device PZ II (pr/b) there is no signal on block P13, the device P4 (pr/b) there is no high voltage. The device P2-1II (l/b) there is no signal of control generators.