

# Results of Infra-Red Surveys

---

## Contents

Summary of Survey.....	2
Church.....	2
Church Hall.....	2
Diagrams of Heat Loss.....	3
Church Diagram showing heat loss figures.....	3
Church Hall – Diagram of heat loss.....	5
Pictures.....	7
Church.....	7
South side (Naive).....	8
South side Chancel.....	8
West Wall.....	10
North Side Chancel.....	11
Vestry.....	13
Church Hall.....	14
Floor.....	14
Meeting room.....	14
Communal Areas.....	16
Food bank room.....	17
Marie’s office.....	18

## Summary of Survey

### Church

Average summary for Church	
Average heat loss were radiator not under window	35%
Average heat loss were radiator was under window	70%
Average heat loss walls	15%
Average heat loss for door with curtains (curtains stored and radiated heat) was	-8%
Average heat loss for door where no curtains used) was	22%
South porch double doors when both shut	5%
1853 old roof on very cold day showed heat loss between rafters.	See photo

Note 1 The walls of church slowly got warmer over the month of the surveys (were very cold at the start (8 degrees) and slowly warmed up during the month, to a point where no heat loss recorded. The outside temperature of the walls remained cold. ) I suspect this contributes to the cold draft people feel when seated near the walls.

Note 2 – If church doors are left open for 20 minutes the temperature around the entrance inside drops 3 to 4 degrees, from 15 degrees even though there are many radiators (floor and standing by the south entrance.)

Note 3 – The edges of the wooden external doors are sealing well and no clear heat loss at the edges.

Note 4 – The south wall radiators in the chancel are not working as well. In particular the one under the window nearest the south porch entrance, number 6.

### Church Hall

Events - Meeting room	
Average heat loss were radiator not under window	33%
Average heat loss were radiator under window	15%
Average heat loss for ceiling	27%
Average heat loss for walls	15%
Floor (when room was well heated)	70%


Maries office	
Heat loss were radiator not under window	27%
Heat loss were radiator under window	15%
Ceiling heat loss	26%

Walls heat loss	27%
-----------------	-----

## Diagrams of Heat Loss

### Church Diagram showing heat loss figures


Church on average air temperature was 14.5-15 Degrees and Most of Radiators 45 degrees



Church on average air temperature was 14.5- 15 Degrees and Radiators 45 degrees

Surface Area	Temp		Temp Diff from Room	Heat loss
Window 1	12		3	20%
Window 2	11.4		3.6	24%
Window 3	13.7	radiator 55.6 degrees	1.3	70%
Window 4	10.2		4.8	32%
Window 5	9.3		5.7	38%
Window 6	13.2	radiator 35	21.8	62%
Window 7	9.7		5.3	35%
Window 8	9.8	radiator 30	20.2	67%
Window 9	na			
Window 10	10.3		4.7	31%
Window 11	10.3		4.7	31%
Window 12	11.3		3.7	25%
Window 13	10.8		4.2	28%
Window 14	12.5	radiator 42.6	2.5	72%
Window 15	10.5		4.5	30%
Window 16	11.1		3.9	26%
Window 17	12.4	radiator 44.6	2.6	72%
Window 23	11.9	radiator 43	31.1	72%
church wall v1	12.9		2.1	14%
church wall v2	13.1		1.9	13%
church wall v3	12.2		2.8	19%
Door D1	14.5	With Curtain in place	0.5	3%
Door D3 - with curtain	16.7	With Curtain in place + plus floor heater by door	-1.7	-11%
Door D3 - without curtain	14.5		0.5	3%
Door D2 (south)	14.3	Both Doors closed	0.7	5%
Door D2 (south)	11.8	Outer door only	3.2	21%

## Church Hall – Diagram of heat loss



Church Hall – Note Meeting Room + Marie's office air temperature was 22 degrees and communal areas 15 degrees (except for the floor when air temp was 30 degrees)


Church Hall – Note Meeting Room + Marie’s office air temperature was 22 degrees and communal areas 15 degrees (except for the floor when air temp was 30 degrees)

Window	Temp	Comments	Temp Diff from Room	Heat loss
	<b>Meeting room</b>			
Window 1	12.5		9.5	43%
Window 2	18.6	radiator below window	3.4	15%
Window 3	13.7		8.3	38%
Window 4	13.2		8.8	40%
Window 5	14.3	Door?	7.7	35%
Window 6	12.8		9.2	42%
wall	17.5	wall by no 6 window	4.5	20%
wall	20	Wall between no 2 -3 window	2	9%
Ceiling	15.2		6.8	31%
Ceiling	15.7		6.3	29%
Ceiling	16		6	27%
Ceiling	16.2		5.8	26%
Floor	14.5		15.5	70%
	<b>Communal Areas</b>			
Window 7 (Kitchen)	9.6	( not heated as much 15 degree air temp during test)	5.4	36%
Window 8 (Ladies Loo)	10.6	( not heated as much 15 degree air temp during test)	4.4	29%
Window 9 (Ladies Loo)	10.3	( not heated as much 15 degree air temp during test)	4.7	31%
Window 10 (Gents Loo)	9.9	( not heated as much 15 degree air temp during test)	5.1	34%
11 (Sherley's office)	9.9	( not heated as much 15 degree air temp during test)	5.1	34%
12 (food bank)	9	( not heated as much 15 degree air temp during test)	6	40%
	<b>Marie's office</b>			
13	16		6	27%
14	18.8		3.2	15%
Marie's office wall	16		6	27%

## Pictures

### Church

Roof on first cold day.



Average temp of 1853 (west end) was 6.6% - Could clearly see the heat being lost between joists.

This was did not show on the new roofs.



## South side (Naive)


Window No 1



Window 2



Window 3 (note there is a radiator under this one)




Window 4





## South side Chancel

Window 5



Window 6 (radiator below window)



Window 7



Window 8



Window 10



West Wall

Window 11



Window 12



Window 13



North Side Channel

Window 14



Window 15






Window 16



Window 17 (radiator under the window)



Window 23




Window 18




Vestry


## Window 19



## Window 21




## Window 22



## Church Hall

## Floor



## Meeting room

### Window 1



### Window 2





**Window 3**



**Window 4**



**Window 5**

**Window 6**





## Communal Areas

### Window 7 - Kitchen



### Window 8 – Ladies Loo

### Window 10 –Gent's loo




## Food bank room

Window 12 (Very little heat in the room)



## Marie's office

Window 14



Wall

