

How to resolve HDMI issues on the Ultra

If you encounter sudden non-recognition or persistent loading (spinning wheel), we recommend upgrading your HDMI ports.

Steps:

1. Go to 'About Device'.

↑ 120B/s
↓ 328B/s 08:17 🌧️ 100%



Account & Settings



Josh Gately



Kadie Smith



unconnected



RTMPS

SRT

SRT

HL

HL



Account(Email) **jiamy@yololi...**



Network Settings



Bluetooth



About Device



Power-down Mode



Version

Upgrade



Language

English >



Keyboard Setting



2. Click 'E-Label'.



About Device

Software Version	Ultra-2.5.0
------------------	-------------

Firmware Version	Yolo-ultra-os-2.4.1
------------------	---------------------

Mac address	72:DB:A4:75:B5:97
-------------	-------------------

Serial Number	u1779c5d5a
---------------	------------

IMEI	864081062402735
------	-----------------

E-Label	>
---------	---



3. Click multiple times within the red box area.

↑ 0B/s
↓ 78B/s

08:21   100%



E-Label

Input: 9V/12V/15V == 3A

Manufacturer: Hangzhou Xingxi Technology Co., Ltd

ADD: Room 112, 112M, Building 1, No. 1818-1, Wenyi West Road, Yuhang Street, Yuhang District, Hangzhou, Zhejiang Province

Contain FCC ID: XMR2022SG865WWF , XMR201903EG25G

Trade mark: YOL  LIV

Place of Origin: Made in China

Certification mark:



4. Click 'Update'.

↑ 0B/s
↓ 0B/s

08:24  5  100%



System Patch Update

HDMI1

Update

HDMI2

Update

HDMI3

Update

HDMI4

Update

Video tutorial:

 Ultra HDMI Update.mov