

I. General information	Loading report
Report # 087	
Emission place: China	
Date: 2019/03/18	

Made by: GDRworld No. 988, Gangwan Street, Dongmei Community, Donghai Street, Fengze District, Quanzhou City, Fujian Province Phone: +86 134 0086 1250 Email: sales@gdr-world.com	Inspector: Guillermo Chavez Phone: +86 134 0086 1250 Email: sales@gdr-world.com
factory contact: Julia Cao (曹丽侠) Phone: +86 512 5866 XXXX Email: shimestXXXX@aliyun.com	Place of inspection: Huatang road, Tangshi town, Zhangjiagang city, Jiangsu Province. Phone: +86-1396246XXXX

Shipper Name:	SUZHOU DEEDO MACHINERY CO., LTD ADD: Yuanjiaqiao, ciudad Jingang, ciudad de Zhangjiagang, Provincia de Jiangsu, China PHONE: 86-13962461986 FAX: 86-512-58662928
Consignee Name:	Company MAVXXXX SA ADD: Ciudadela Guayaquil, sector Kennedy Norte, calle Alberto Nuques N: XXXX
Shipping port FOB:	SHANGHAI
Description:	SS-550 Paper Straw Machine Production Line • Paper frame (1 piece) • Glue system (1 piece) • Straw mold 6mm 8mm 10mm 12mm (1 piece) • Manufacture and cutting of straw (1 piece) • Paper paper straws (for test) • Straw collection conveyor (1 piece) Inline Straw Paper Auxiliary Machine • SZ450 cutting machine (1 piece) • JH03-P Single Packing Machine (1 Piece) • Paper straw type paper (2.7 tons) ◦ or 2100kg 120gsm paper ◦ or 600kg of 60gsm paper • 529kg paper packing machine (for test) • Paper straw glue 6 barrels 250kg (test)
Total weight:	6024kgs
Pieces:	16
Factura comercial N°:	DD20190219

II. INSPECTION SUMMARY		
OVERALL INSPECTION RESULT		
☒ PASSED	FAILED	ON-HOLD
Note 1: N/A=Not Applicable; H=On-Hold; P=Passed; F=Failed		
Category	P/F/H/N/A	Remark
Inspection Category (Part A)	P	
Loading Location & Weather (Part B)	P	
Securing Materials Used (Part C)	P	
Container & Loading Details (Part D)	P	

III. REMARK	
General Remarks:	
1.	Factory disassembled the Paper Straw Machine Production Line chips frying line into many parts and packages. Inspector can count the main parts only. The factory said all the parts were included in the packages.
2.	Found no shipping mark on some packages, there is shipping mark on wooden only.

IV. CLIENT SPECIAL REQUIREMENT		
No.	Client Requirements	Result:
1.	/	
Remark:	/	

Note:

1. This report reflects our findings at the time and the place of inspection based on random samples selected.
2. This inspection was carried out to the best of our knowledge and abilities, and our responsibility is limited to the exercise of reasonable one.
3. This report does not relieve the sellers from their contractual obligations nor does it prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our inspection or occurring thereafter.
4. This report does not evidence shipment.
5. Our services are subject to the General Conditions of GDR-world.com, which is shown at our website and can be sent to you upon written request.

.....

Please find our inspection details from the next page (Section A – G).

A. Inspection category				
Inspection category	Judgement result			
	Y (✓)	N (✓)	N/A (✓)	Remark
A. Check the status of containers, are they intact and are they suitable for loading in accordance with international container safety regulations.	✓			
B. Check the quantity, size and shipping mark of the products according to the packing list for conformity with the shipping documents and commercial documents.	✓			Found no shipping mark on some packages, there is shipping mark on wooden only.
C. Check the strength of the rope, whether there is any wooden material for the barrier between the bundled products, and whether it is the same in the container, to avoid damage and bending of the products. Supervise the loading, placing and reinforcement of products into containers.	✓			
D. Supervise whether fumigation is carried out after loading, whether there is a fumigation seal on the surface of wood material, and check whether there is a fumigation certificate.	✓			Factory used some small wood blocks as securing materials, but they can't provide the fumigation certificate for these wood materials.
Remark:				

B. Loading Location & Weather				
Loading Location:	☒ Factory	☐ Bonded area	☐ Warehouse	☐ Other
Weather:	☒ Sunny	☐ Cloudy day	☐ Rainy	☐ Other
Sheltered:	Yes		☒ No	
Remark:				

C. Securing Materials Used	
C-1	wire rope: Yes
C-2	Choking Materials: Yes, wood
C-3	Wedging Materials: Yes, steel

Reference photos



D-1. Container & Loading Details

Container Type	Container No.	Seal No.	Loaded Cargo	
			Item No.	Loaded Qty
20G1	OOLFNQ7390	OOLU 105581X	Paper Straw Machine Production Line	2
Total:				2
Result:	☒ PASSED (Conformed)		☐ FAILED (refer to remark)	
	☐ ON-HOLD (refer to remark)		☒ N/A (Not Applicable)	
Remark:				

Loading Photos

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.





The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.



End of Report

The report reflects the findings at the time and place of inspection. This report does not relieve the sellers/manufacturers from their contractual liabilities or prejudice the buyer's right for compensation for any apparent and/or hidden defects not detected during our random inspection or occurring thereafter. This report does not evidence shipment.