MAINTENANCE JOB CARD
ACS TASK: AM.II.I.S10 Inspect electronic equipment shock mount bonding jumpers for resistance.
ATA CODE: 20

REFERENCES:

FAA-H-8083-31B **Bonding** on page 11-73
AC 43.13-1B paragraph 11-188
AC 43.13-1B paragraph 11-189

TOOLS/MATERIALS/EQUIPMENT:
Sensitive Multimeter

CONSUMABLES:
None

PROCEDURES:
1. Perform resistance check of bonding jumpers for resistance as assigned by instructor/examiner.