Show Networks and Control Systems Second Edition (2017) Errata

Page 25

The top of the speaker graphic is cropped.

Page 33

The section:

Proprietary implementations from a few manufacturers became de facto standards and are good examples of typical control implementations. Two of these are covered later, in the “Sony 9-Pin Protocol (Obsolete),” on page 334, and the “Sony 9-Pin Protocol (Obsolete)” section on page 334.

Was an editing mistake and should read:

Proprietary implementations from a few manufacturers became de facto standards. For example, the “Sony 9-Pin Protocol (Obsolete),” on page 334.

Page 146

On the null modem graphic, the arrowheads should go only from TX to RX and not both directions.



Page 276

I have a capitalization typo in the MIDI Time Code cross reference.

In addition to the non-real-time messages we've covered, there are also a number of globally defined, real-time SysEx messages, some of which are covered in their own chapters MIDI TIme Code (Chapter 25), MIDI Show Control (Chapter 23), and MIDI Machine Control (Chapter 24):

Page 279

I have a mistake on the right hand diagram, the "Slave #3" on the left should be "Slave #1".

