

MAINTENANCE JOB CARD

ACS TASK: AM.III.A.S7 Inspect and rig cable and push-pull engine controls.

ATA CODE: 76

REFERENCES:

[FAA-H-8083-32B](#) Connections & Adjustments Page 8-10 and 8-1

TOOLS/MATERIALS/EQUIPMENT:

Carburetor and Throttle/Mixture/Carb Heat Training Aid

CONSUMABLES:

None

PROCEDURES:

1. Inspect Carburetor and Throttle/Mixture/Carb Heat Training Aid for proper throttle and mixture adjustments.

