MAINTENANCE JOB CARD
ACS TASK: AM.II.K.S18 Perform a continuity test to verify the condition of a conductor.
ATA CODE:

REFERENCES:
AC 43.13-1B
FAA-H-8083-30B
FAA-H-8083-31B
Measuring Continuity with a Digital Multimeter Video

TOOLS/MATERIALS/EQUIPMENT:
Wire assigned by the instructor
Multimeter

CONSUMABLES:

None

PROCEDURES:

1. Perform continuity test and verify condition of conductor assigned by instructor/examiner.