


To: Update to PR40.1 AS OF 2/10/23 (step by step) Verify Version :


[TSB 08-095-22](#) (PR39.9)

[TSB 08-095-22](#) REV A (PR40.1)

Press bottom 2 corners of the screen for 10 seconds




Select system information



Select radio part info

Look at the application version




If at LR34.2 OR HIGHER update to PR39.9

IF NOT. Update using the order below. See attached TSB AT TOP!!!

Download the needed updates to a USB in FAT32 format

Uncompress file and copy the VP4R_Update folder only into the USB drive

Plug into truck. The truck will display the following




Select update now only if you will not be driving. Update may stop if you drive.

Screen will display



Once it finishes the screen will go blank then display



Install only if needed in this order -

[UAX KR20](#) (link not working)

[UAX NR28](#) (link not working)

[UAX LR34](#)

[UAX PR39.7](#)

[UAX PR39.9](#) (different from 39.6 or 39.7) YOU WILL NOT BE ABLE TO USE OFFROAD PAGES

[UAX PR 40.1](#)

To confirm install keep usb stick in and put truck in acc or run



7:47

--out.



Software Update



Current: USA-SBX-12.1-PR-39.9.0-20220308-P011
Update to: USA-SBX-12.1-PR-39.9.0-20220308-P011

Update not available
to same software version.

Ok



Unknown
Not Provided
Unknown
Unknown



Media

Phone

Controls

Apps

Climate

Nav

Back Cam



