## Meeting Minutes (December 1, 2017)

- 10am to 7:30pm
- Fixed part of wall detection DFS code
- Changed left and right turn thresholds
- Combining radio with the rest
- Change verilog code
- Work on treasure sensors

•