

S/N	WORK DESCRIPTION	THREATS	WHO MIGHT BE HARMED OR EXPOSED	CONSEQUENCES	CONTROL OF HAZARDS	RECOVERY
16-A	WORK AT HEIGHT	1. Poor platform/ladder. 2. Commencement of work without conducting – J.H.A. 3. Absence of competent safety & supervisory personnel. 4. Excess human load on platform/ladders. 5. Poor housekeeping. 6. Absence or wrong posting of directional caution signs. 7. Use of an unapproved platform / ladder. 8. Working without a safety harness/ belt. 9. Working without relevant P.P.E. 10. Personnel under platform /ladder. 11. Overload of platform / form with materials. 12. Other safety lapses.	Personnel involved in task execution, work materials, other personnel on site and facility / environment.	1. Injury to personnel. 2. Damage to materials /equipment. 3. Injury to workers leading to L.T.I or death. 4. Fall by personnel due to tripping hazards or collapse of platform / ladder. 5. Damage to environment & installations. 6. Stress.	1. Conduct J.H.A before task execution. 2. Plan tasks in advance of execution. 3. Ensure good housekeeping. 4. Competent personnel to erect platforms. 5. Use an approved platform / ladder. 6. Dedicate competent safety and supervisory personnel during task execution. 7. Post appropriate directional caution signs. 8. Dismantle/remove platform or ladder soon after task execution. 9. Personnel to use relevant harness/PPE. 10. Observe platform / ladder S.W.L and other safety rules. 11. Restrict traffic under the platform.	Provide First aid resources, effective means of communication and medivac.