


ขั้นตอนการติดตั้ง Driver HMI ใน Windows 10

1. ติดตั้ง Driver HMI ใน Win10

- เสียบสาย USB HMI(USB DEVICE) to PC
- เช็คว่าใน Device manager Port(COM & LPT) มันจะขึ้น
USB Device (COM3)
- ซึ่งมันติดต่อกับ PC ได้ แต่ยังไม่มีการติดตั้ง Driver
- จะต้อง Update Driver ให้มัน แต่ก่อนที่จะ Update จะต้อง Disable driver signature enforcement ก่อน.
 - 1) click "Start button" -> "Setting"
 - 2) Click "Update & Security"
 - 3) Click "Recovery" -> "Restart now"
 - 4) PC Restart
 - 5) Click "Troubleshoot" -> "Advanced options"
 - 6) ที่ Advanced options Click "Startup Setting"
 - 7) ที่ Startup Setting Click "Restart"
 - 8) PC Restart
 - 9) ที่ Startup Settings กดเลข 7 (Disable driver signature enforcement)
 - 10) Re-start PC

2.Update Driver

1) Click USB Device -> "Update Driver"



2) Click "Browse my computer for driver software"

3) Click "Let me pick from a list of available drivers on my computer" -> "Next"

← Update Drivers - USB 串行设备 (COM4)

Browse for drivers on your computer

Search for drivers in this location:

C:\Program Files (x86)\CoolMay\CoolMayHMI

Browse...

☒ Include subfolders

→ Let me pick from a list of available drivers on my computer

This list will show available drivers compatible with the device, and all drivers in the same category as the device.


Next

Cancel

4) Chose "CoolMayHMI" -> "Next"




5) Chose "Install this driver software anyway"




3. ที่ Device manager

1) Network adapters -> จะมี "CoolMayHMI" โขวขึ้นมา



4.Set IP Address ของ Network CoolMayHMI

1) Open Neywork connection




2) Click רצו "Network CoolMayHMI" -> Properties

3) Double-click -> "Internet Protocol Version 4(TCP/IPv4)

4. Input IP Address: 222.222.222.6

Subnet mask:255.255.255.0




5) Click OK


5.ON Run as administrator CoolMayHMI

1) Click  CoolMayHMI icon

2) click Properties -> "Advanced"



3) Click Mark ON Run as administrator



4) Click OK