

5s +Safety Standardize
Farmersville Engineering Academy
Undeniable Precision Experts

5s +Safety Standardize

- Workstation table top and floor
- Tools and Parts Put Away
- Drawers Placed Back
- Eye Protection - All Times
- 5s Audit - Weekly

“Your Commitment to Safety and Efficiency Matters!”

1. Clean Workstation Table Top & Floor

- Keep surfaces free of clutter and debris
- Ensure the floor is clean and parts are put away

2. Tools and Parts Put Away

- Store tools and parts in designated locations
- Return items after use

3. Drawers Placed Back

- Ensure all drawers are closed
- No items left out or misplaced

4. Eye Protection - All Times

- Wear safety goggles or glasses at all times
- Ensure eye protection is in good condition

5. 5S Audit - Weekly

- Conduct regular audits for compliance
 - Address any issues promptly
-