



Arkadelphia Public Schools
Director of Support Services
Jimmy King



March Maintenance Report

- May Construction has repaired the erosion problem on the south side (Main St side) of the Peake track. The large hole in the curve of the track has been filled in and concrete and rip-rap has been installed on the hillside to stop further erosion.
- A water leak under the slab in the kitchen at Perritt Primary has been repaired. We were fortunate that we were able to locate it and only had to jackhammer a small 12"X12" area to get it repaired without having to jackhammer across the entire length of the kitchen floor.
- The compressor on the walk-in cooler at AHS went out and had to be replaced.
- A heat trace line on a hot water tank in the gym at Goza went out. We've diagnosed it as a bad controller.