



**OPEN**  
Compute Project

Partial Width, Density Optimized HPM Form  
Factor (M-DNO) Base Specification

# M-DNO\_R1\_v1p0 Errata Document

January 19, 2023

## Errata #1

Impacted Specification Section(s): [10.13.2 – Direct Dock E1.S](#)

Impacted Specification Figure(s): [Figure 35: Direct Dock E1.S in Custom Zone](#)

Impacted Reference CAD: [m-dno-type4-221014-E1s.stp](#)

[m-dno-type4-221011-all-conns.stp](#)

The provided recommended dimensioning in **Figure 35** is incorrect and results in a collision between the required OCP NIC R3 location and one of the E1 modules.

The updated recommendation is provided below. Note that dimensioning has been changed to reference the centerline of Datum E in the SFF-TA-1002 connector specification. Additionally, the new location allows for either 1C or 2C connector variants to be placed.

*ECN 1 Figure 35 Update*

