



Remediation Plan Recommendations

For test points at or above 5 pbb lead content, per §160.077, secure water and discontinue use until remediated unless testing proves that flushing will provide water below 5ppb.

9 outlets were remediated and retested. 7 of those were successfully remediated. The remaining two are secured with signage in place and are slated for removal and remodeling.

All requirements have been met. No further actions required this reporting cycle.

Items listed in gray require no further action. NS=No Sample, ND=None Detected

Initial	Flus h	Remedia l	Location	Remediation Recommendations
6.32	1.56	2.06	Hand sink in room 25	No Further Action Required
5.22	1.54	NS	1st RR sink girls rr across from room 16	Signage in place
5.59	1.28	NS	2nd RR sink girls rr across from room 16	
23.2	5.05	3.5	Hand sink in room 27	No Further Action Required
6.88	3.26	3.5	1st RR sink in boys rr -Café	
9.12	4.02	3.68	2nd RR sink in boys rr -Café	
7.22	2.93	3.06	1st RR sink in girls rr -Café	
8.76	3.4	2.96	2nd RR sink in girls -Café	
5.11	3.71	NS	Hand sink girls locker room 11	Signage in place
6.56	2.55	NS	hand sink boys locker room 14	
19	1.98	NS	1st Sink in boys RR across from room 36	
22.7	1.86	NS	2nd Sink in boys RR across from room 36	
18.3	2.13	17	Hand sink in room 37	Outlet secured/removed
8.52	1.28	NS	1st Sink in girls RR across from room 38	Signage in place
8.15	1.33	NS	2nd Sink in girls RR across from room 38	
8.19	ND	NS	Sink in boys RR in teacher workroom 39	
5.58	ND	NS	Sink in girls RR in teacher workroom 39	
11.6	2.28	10.5	Sink in teacher workroom 39	Outlet secured/removed
9.14	22.4	3.22	HB hydrant in concession stand	No Further Action Required

If you desire further health information, you can contact your county health department:

Monroe County Health Department

monroecountyhealth.com [310 Market St, Paris, MO 65275](https://www.google.com/maps/place/310+Market+St,+Paris,+MO+65275/@39.2925,-91.2925,15z) [\(660\) 327-4259](tel:6603274259)