








Поз.	Наименование	Кол.	Материал	Примеч.
1	Основание	1	Чугун	
2	Ролик	1	Сталь	
3	Шина	1	Резина	
4	Болт М10х60	1	Сталь	
5	Гайка	1	Сталь	
6	Шайба	1	Сталь	
Ролик				
Чертил				
Проверил				
Школа		кл.		№

Сборочный чертеж




Все размеры указаны в мм




Поз.	Наименование	Код	Материал	Примеч.
1	Основание	1	Сталь	
2	Стержень	1	Сталь	
3	Чертилка		Сталь	
4	Каретка		Сталь	
5	Гайка		Сталь	
6	Винт зажимной		Сталь	
7	Винт М2,5х8		Сталь	
Рейсмус				
Чертил				
Проверил				
Школа	к7.			№

Упражнение

1. Прочитать сборочный чертёж по алгоритму.
2. Выполнить задания, указанные в карте.



0194. 0803. 000



0194. 0803. 000				Резьбовое соединение				группа	
Изм./лист	№ докум.	Подп.	Дата	Лист	Масса	Масштаб	Лист	Масса	Масштаб
Разраб.	ФНД	Подп.	Дата	1	153	1:1	1	153	1:1
Проф.	ФНД	Подп.	Дата	2			2		
Т. контр.									
Н. контр.									
Умб.									

Revised 2007	2007



Technical drawing of a mechanical part, showing a top view and a side view.

Top View:

- Overall dimensions: 100 (width) x 160 (height).
- Central feature: A circular cross-section with a central hole and four radial slots.
- Central hole diameter: $\phi 8.5$.
- Slot width: 4.
- Four corner holes are present.
- Section lines A-A and T-T are indicated.

Side View:

- Shows the circular cross-section of the part.
- Dimensions: 140 (width of the central feature) and 160 (height of the part).



1 Размеры для справок

