

Date	Publ	Ann	Log	Key	Shop	Tach	TTAF	TSMOH	Description	Actual	Picture	Expected	Notes
									Total	\$39,371.9			\$51.38 per hour
3/11/2015	x				Fletch	2583.13	4051.87	23.45	Annual (Engine)				https://drive.google.com/file/d/1wC26HJ0RtUuLjgawtAue330JmBvieswQwps/view
3/11/2015	x	x		AF	Fletch	2583.13	4051.87	23.45	Annual (Apr-buy inspection) @ Fletch				
3/12/2015	x				Fletch	2583.13	4051.87	23.45	Annual/Pre-buy @ Fletch	\$1,500.00			1468.74 Tach to TT offset; source: Annual 03/11/2015.
5/16/2015	x				Vogt @ KJ	2583.13	4051.87	23.45	Gary Vogt: time for oil change, baffie repair, some light inspection	\$100.00			
5/16/2015	x				Vogt @ KJ	2583.13	4051.87	23.45	Case of 15W50, Oil filter	\$130.00			
5/30/2015	x				Vogt @ KJ	2600	4069.74	40.32	Gary time for flap switch inspection and cleaning, tail wiring inspection	\$100.00			
6/5/2015	x			AF	PA@KPA	2631.14	4099.88	71.46	IFR cert; COM2 repair attempt; NAV2 head unit replaced	\$1,292.50			Peninsula Avionics: NAV2 fixed. COM2 marginal improvement.
7/3/2015	x				PA@KPA	2650	4118.74	90.32	COM1 repair attempt; replace COM1 antenna cable, COM1 bench test and good	\$235.00			Peninsula Avionics: COM1 Marginal improvement.
7/6/2015	x				Vogt @ KJ	2650	4118.74	90.32	repairs	\$850.00			\$100 parts, \$750 shop time
7/15/2015	x				Damm	2776	4244.74	216.32	Update Jeppesen 430W Garmin GPS IFR DB	\$350.00			1 yr sub
8/1/2015	x				Damm	2776	4244.74	216.32	Case of 15W50, Oil filter	\$130.00			Thanks Kirtal!
8/1/2015	x				Damm	2776	4244.74	216.32	Parts and tools required for self-serve oil changes	\$50.00			
8/12/2015	x			E	Rossi@KF	2697.86	4166.6	138.18	Oil change, engine wash, Rossi	\$370.00			Not quite sure about the date
8/17/2015	x				PA@KPA	2700	4168.74	140.32	Update 430W Terrain/Obstacle DB	\$110.00			Peninsula Avionics. Will never return.
8/18/2015	x			AF	Vogt @ KJ	2709.2	4176.94	148.52	Replace both rubber return springs (Gary @ KALUN)	\$80.00			Cash
8/27/2015	x			E	Rossi@KF	2742.1	4210.94	182.42	primer!; reduce timing from 28/27 to 25 TDC; increase mix at full mix.	\$1,260.00			Rossi: Poor work + arrogant
11/6/2015	x				Damm	2776	4244.74	216.32	Buy & install port side strobe guard. Painted several coats.	\$350.00			Pilot install.
11/8/2015	x				Damm	2776	4244.74	216.32	Wheels Farmhouse Plus P88P1L	\$235.00			
11/8/2015	x				Damm	2776	4244.74	216.32	Exterior screw kit, A45B	\$57.75			
11/9/2015	x				Damm	2780	4248.74	220.32	AeroShell 15W50 Case	\$113.55			AircraftSpruce; incl. s&h, taxes
11/22/2015	x				Damm	2790.02	4258.76	230.34	Oil change (no filter)	\$0.00			
11/30/2015	x				Vogt @ KJ	2795	4261.74	235.32	AeroShell 15W50 Case-Oil Filter	\$117.87			
11/30/2015	x				Vogt @ KJ	2798	4266.74	238.32	Concorde Sealed Battery RQ25XC	\$274.07			
2/4/2016	x			AF	Rossi@KF	2838.28	4307.02	278.6	All linings on both brakes @ Rossi No pressure on L brake; Rossi rebuilds pilot left side brake master. Rush "bottom up". I can't help but wonder why the master suddenly fails following the linings service.	\$350.00		See	
2/8/2016	x			AF	Rossi@KF	2838.28	4307.02	278.6	following the linings service.	\$300.00			
2/16/2016	x				Rossi@KF	2851	4319.74	291.32	Fails to start. Sparkplugs cleaned	\$750.00			Estimate...
3/20/2016	x				Rossi@KF	2851	4319.74	291.32	Oil for last three visits. Brakes, timing, sparkplug cleaning	\$1,200.00			Rossi smashes the nose wheel pant. Never go back.
3/20/2016	x				Rossi@KF	2851	4319.74	291.32	Fails to start: Magnets sent to Ly-Con for rebuild	\$247.88			
3/27/2016	x				Rossi@KF	2852	4320.74	292.32	ZEFTRONICS VOLT REG R15V00-A	\$912.00			Fine wire spark plugs; main benefit is more time between cleanings.
3/27/2016	x				Rossi@KF	2852	4320.74	292.32	Fine wire UREM3MS	\$207.00			New tire due to deer emergency braking
3/27/2016	x				Rossi@KF	2852	4320.74	292.32	Goodyear Flight Custom 6x6x6	\$45.95			
3/27/2016	x				Rossi@KF	2852	4320.74	292.32	Lockguard tube	\$163.50			Old brake rotors below or at minimum thickness
3/27/2016	x				Rossi@KF	2852	4320.74	292.32	RAPCO BRAKE DISC RA164-02000 (both)	\$5,237.60			Annual: voltage regulator, main wiring, 60-amp, brake rotors, wheels
4/6/2016	x			AF	Vogt @ KJ	2852.35	4321.09	292.67	Annual: voltage regulator, main wiring, 60-amp, brake rotors, wheels	\$5,237.60			repacked
4/6/2016	x			E	Vogt @ KJ	2852.35	4321.09	292.67	Annual: (Engine)	\$300.00			https://drive.google.com/file/d/1MwvFu0e728k6el_gdP9q6tdnGcDyQwvQwps/view
4/16/2016	x				AT@KJAC	2856.9	4325.64	297.22	Altitude encoder wiring fix at Airtronics	\$608.00			
4/19/2016	x				AT@KJAC	2861.49	4330.23	301.81	Repl. Alt encoder, transponder, add cable adapter	\$113.55			
5/30/2016	x				Damm	2893.6	4362.34	333.92	Oil change, Case of oil	\$100.00			Flap switch came loose; repaired. Analyze strobe failure. Loan R side
6/11/2016	x				Damm	2900	4368.74	340.32	part bushing	\$133.55			One order of oil, previous order of filter
8/1/2016	x				Damm	2920.28	4398.02	369.6	Oil change, filter change, Case of oil	\$720.46			
8/17/2016	x				Damm	2940.55	4409.29	380.87	Parts from Fletch: Pair wheel pants, L side navistrobe cover, strobe bulb	\$1,000.00			
8/27/2016	x			AF	Vogt @ KJ	2963.43	4432.17	403.75	Throttle cable replacement, nav-strobe-lens install, L wheel brake line rebuild	\$114.98			Incl \$22.10 shipping
9/28/2016	x				Damm	2980	4448.74	420.32	Oil case from Aircraft Spruce	\$105.00			
9/30/2016	x				Damm	2980	4448.74	420.32	Parts from Fletch: Wingtip Strobe power supply (NOT INSTALLED)	\$0.00			
10/2/2016	x				Damm	3002.71	4471.45	443.03	Oil change (no filter)	\$0.00			
10/12/2016	x				Damm	3006.33	4477.07	448.65	Replaced R engine strobe bulb	\$5.43			Shipped USPS first class. Had fun installing this one!
12/4/2016	x				Damm	3040	4508.74	480.32	PTT switch \$2.62 @ Aircraft Spruce; Part # 11-04470	\$0.00			
12/4/2016	x				Damm	3043.49	4512.23	483.81	Oil and oil filter change	\$641.89			Juan. Came pre-drilled.
1/23/2017	x				Damm	3064.25	4532.99	504.57	Spinner from Fletch	\$145.99			Merchandise: \$110.50 Shipping: \$28.83 Tax: \$8.56
3/20/2017	x				Damm	3070	4538.74	510.32	Oil case, Filter, from Aircraft Spruce	\$363.87			Merchandise: \$337.70 Shipping: \$0.00 Tax: \$26.17
4/9/2017	x				Damm	3103.14	4571.88	543.46	Oil & filter change	\$5,360.60			\$5,000.00 \$500 deposit, \$200 new alternator (not installed), \$160 gas.
5/8/2017	x				Damm	3117.32	4586.06	557.64	L main tire&tube, nose tire&tube	\$0.00			
5/15/2017	x			AF	Vogt @ KJ	3117.32	4586.06	557.64	Annual: Gary Vogt. Shiny new wheel pants. Oil, fuel, air filters. Baffle fix. Much tube. All wheel bearings.	\$5,360.60			
5/15/2017	x			E	Vogt @ KJ	3117.32	4586.06	557.64	7780, 7880, 7890, 7890	\$0.00			https://drive.google.com/file/d/1MwvFu0e728k6el_gdP9q6tdnGcDyQwvQwps/view
6/18/2017	x			E	Damm	3123.61	4592.35	563.93	Remove and replace alternator, MG signoff.	\$0.00		\$0.00	
7/22/2017	x				Damm	3152.94	4621.68	593.26	Oil change	\$0.00			
10/14/2017	x				Damm	3224.24	4692.98	654.56	Oil change (filter incl), AeroShell 15W50	\$0.00			
12/4/2017	x			AF	High Des	3232.05	4700.79	672.37	ADS-B GTX 345 installed @ High Desert Avionics	\$7,227.05		\$8,700.00	Labor (1800) Box (4495) Encoder (265) Tax (440.40) Antenna (126.75)
12/4/2017	x			AF	High Des	3232.05	4700.79	672.37	IFR 91.411 High Desert Avionics	\$218.95			pilot install and test
3/29/2018	x			E	Damm	3265.08	4733.82	705.4	Oil change	\$1,627.01			Failure at take-off @ KMOD, expense due to wish to get on the road again quickly.
4/7/2018	x			AF	Damm	3270.71	4739.45	711.03	Replace Voltage Regulator w/Zeftronics R15V00-A	\$202.00			Thread failure
4/18/2018	x			E	Sky Trek	3276.93	4745.67	717.25	R&R Left magneto PIN 4371, new SN 17120799	\$4,738.00			
4/23/2018	x				Damm	3280	4748.74	720.32	Dipstick LW16783-18 Annual: New oil #1, vac pump, new SkyTec 149-NL starter, muffler shroud, oil temp gauge, dipstick tube dx, all belt tension fix, switches fix, AP fix, cowd patches, oil leak fix	\$4,738.00			Performed 50hr inspection on R mag; inspect L mag for aberrant
6/22/2018	x				FileWing	3296.71	4765.45	737.03	signal.	\$108.80			
7/31/2018	x			E	FileWing	3308.5	4777.24	748.82	signal.	\$108.80			