

Box #	MODEL	IN BOX?	Price (NEW)	Reduce by %	Clearance Price	ENCLOSURE ADD-ONS	NOTES	Pictures			Sold?
1	AL272213	Y	\$589.00	25.00%	\$441.75		Top left door has markings.	Pic 1	Pic 2	Pic 3	
2	AL272213	Y	\$589.00	25.00%	\$441.75		Surface scratches on front and side.	Pic 1			
3	AL272213	N	\$589.00	25.00%	\$441.75	Comes with plate	Discoloration.	Pic 1			
4	AL272213	N	\$589.00	25.00%	\$441.75	Comes with plate	2 Holes on front and side.	Pic 1	Pic 2		
5	AL161610	Y	\$483.00	25.00%	\$362.25	AL INS	Dent on side, Bent sunshade with few scratches, Bent hinge.	Pic 1	Pic 2	Pic 3	
7	AL272213N	N	\$589.00	25.00%	\$441.75	No vents, No logo	Bent on sunshade.	Pic 1			
8	AL272213	Y	\$589.00	25.00%	\$441.75	AL INS	Surface scratches on back and sunshade.	Pic 1	Pic 2		
9	AL272213	Y	\$589.00	25.00%	\$441.75	AL INS	Marking on top, scratch on front and top.	Pic 1	Pic 2		
10	AL272213	N	\$589.00	25.00%	\$441.75	No logo	Needs bracket and scratches on front.	Pic 1			
12	AL272213	N	\$589.00	25.00%	\$441.75		Markings on top and both sides and back, Scratches on the front.	Pic 1	Pic 2		
14	AL191912	N	\$573.00	25.00%	\$429.75	No plate, No bracket	Scratch on top, Missing door screw.	Pic 1	Pic 2		
15	AL272213	N	\$589.00	25.00%	\$441.75	AL INS	Scratch on side and back, Discolored on top.	Pic 1	Pic 2		
17	AL272213	N	\$648.00	25.00%	\$486.00	With fan	Brackets already mounted, No doorlock (AL latch).	Pic 1	Pic 2		
18	AL272213	N	\$589.00	25.00%	\$441.75	AL INS	No plate, No bracket, Chemical damage inside with scratches on front.	Pic 1	Pic 2		
19	AL272213	Y	\$589.00	25.00%	\$441.75	AL INS	2 Big scratches on top and front.	Pic 1	Pic 2		
20	AL272213	Y	\$589.00	25.00%	\$441.75	AL INS	3 Scratches on front and on the side.	Pic 1	Pic 2		
21	AL272213	Y	\$589.00	25.00%	\$441.75	AL INS	2 Big scratches on top and one on side.	Pic 1			
29	AL161610	N	\$483.00	25.00%	\$362.25		Top not welded. Back plate missing.	Pic 1			
35	AL202222	N	\$773.00	25.00%	\$579.75		Scratch on the top. Glue on the bottom.	Pic 1	Pic 2		
36	AL272213	N	\$589.00	25.00%	\$441.75		Dent on sunshade.	Pic 1			
37	AL272213	N	\$589.00	25.00%	\$441.75		Logo upside down.	Pic 1			
38	AL272213	N	\$589.00	25.00%	\$441.75		No logo.				
39	AL272213	N	\$589.00	25.00%	\$441.75		Crooked logo on bottom?	Pic 1			
40	AL272213	Y	\$589.00	25.00%	\$441.75		Broken sunshade weld, bottom scratches.	Pic 1			
41	AL191912	N	\$573.00	25.00%	\$429.75		No logo, no AL INS.				
43	AL191912	Y	\$459.00	25.00%	\$344.25		Deep scratch on bottom of can.	Pic 1			Demo
46	AL191912	N	\$573.00	25.00%	\$429.75	No INS, backplate, bracket	Major denting and warping of can.	Pic 1	Pic 2	Pic 3	
47	AL191912	Y	\$573.00	25.00%	\$429.75	No backplate, bracket	Large dent on side, small dents under mounting bracket	Pic 1	Pic 2		
48	AL161610	N	\$483.00	25.00%	\$362.25	No bracket	Dent on top, scrape on door, has a latch	Pic 1	Pic 2	Pic 3	
49	AL161610	N	\$483.00	25.00%	\$362.25	Has latch	Dent on door, scratch	Pic 1	Pic 2		