

Infrastructure & Port Services		
Critical Terminal Data	Chris Gardner, Executive Director Eastport Port Authority 141 Water Street Eastport, ME 04631 207-853-4614 director@portofeastport.org	LAT 44° 54' 21"N LON 66° 58' 59"W
		Up to 800' +/-* *Additional based upon draft considerations
Piers & Gangways	Breakwater Pier (East) 400' including 2 mooring dolphins at 600' with a mean low water depth of 45'. Accommodates ships up to 800' +/-. • 2-8' diameter Yokohama fenders. • Two-tiered aluminum gangway system, accommodating most vessels gangways at 12 degrees or less through all tides. Breakwater Pier (North) 200' floating dock for ships under 275' and/or tendering operations (ship uses its own access). 80' access ramp for floating dock to main pier.	
Tugs	Full tugboat services onsite—operated by Portland Tugboat (207) 772-4791.	
Port Services	✓ Customs & Border Protection ✓ US Coast Guard Station ✓ Port Authority Offices ✓ Full Ship Agency services ✓ Linesman & Security ✓ Year-round docking capability ✓ ISPS/MTSA Compliant (46 CFR 105) ✓ Fueling capability ✓ Potable Water ✓ Fresh water, sewage & waste disposal (international waste included) ✓ Accommodating to ship maintenance and repair operations with on-site equipment services	
Guest Services	Direct walking access to downtown sites and activities from berth. ✓ Visitor information & Welcome Center ✓ On-site Restrooms ✓ Free Wi-Fi ✓ Shuttle/Tour bus — locally owned and operated ✓ Destinations North America partnered operation ✓ Customizable tour packages ✓ Water/Tour Bus Access to Roosevelt International Park	

	✓ Traverse “Old Sow” Whirlpool tour ✓ Whales, Marine Life, Birds & Local Maritime History ✓ Additional Maritime / Fishing Tour activities – Kayak friendly ✚ 25 miles Calais Regional Hospital / 1-mile walking to Eastport Healthcare Clinic/Pharmacy ✈ 1-mile Eastport Municipal Airport 120 miles Bangor International Airport
Planned Upgrades	N/A
Notional Projects	N/A

Climate	
Weather	Eastport Summers are comfortable and sometimes cool, the Winters, however are very cold with significant snow. It is partly cloudy year-round. The wettest month is November with about 4.2 inches (106 mm) of rain. February is the driest month averaging 1.8 inches (45 mm) of rain. June, July and August are similarly dry at about 2.8 inches of rain (66 mm). The windier part of the year is October to April, with average wind speeds of 9.1 MPH from the North or West. The calmer time of year is from April to October with winds predominately from the South at 6.5 MPH on average. Fog is present on average 112 days each year with a minimum occurrence during mid-Winter and a maximum during July and August. The warmest month is July with an average high of 70°F and an average low of 56°F. The coolest month is January with an average high of 30 °F and an average low of 14 °F.

Navigation	
Approach	• Eastport is located near Passamaquoddy Bay and lies directly on Western Passage and Friar Roads, which is all adjacent to the Bay of Fundy. • The approach starts from a Traffic Separation Scheme with in-bound and out-bound traffic to St. John NB bisected by a Separation Zone. Deep draft vessels utilize a Vessel Traffic Service (Marine Communications and Traffic Services (MCTS)) located in Halifax, NS. • Direct port access is via Head Harbour Passage which is a deep and clear fairway, about 4 miles long, that follows the Northwestern side of Campobello Island from the sea to Friar Roads.

	• The port is unique in that the international boundary with Canada divides Friar Roads and Western Passage. The entire length of the transit from the pilot station to Western Passage/Friar Roads is in Canadian waters. • Use NOAA charts 13396 and 13260. • Note that the offshore approaches to Eastport are an endangered Right Whale habitat.
Channel Controlling Depth	• The approach channel has water depth exceeding 140'. • No air-draft restrictions.
Depth at Dock	45'
Under Keel Clearance	Due to ample water depths Under Keel Clearance is not a concern.
Tidal Range	20'-24' on average.
Max Current	Head Harbour Passage current can attain a velocity of 5 knots at times. The flood sets strongly Westward toward the islands about 1 mile Northward of Campobello Island. The ebb generally sets in a reverse direction.
Anchorage	There are no Federally designated anchorages, however, Friars Bay (off Campobello Island) offers shelter and good holding ground. It should be noted that this location is in Canadian waters.
Pilots	Pilotage is compulsory for all foreign vessels and U.S. vessels under register in the foreign trade drawing over 9'. There are two pilot boarding areas: • The pilot boarding station is about 1 mile Eastward of East Quoddy Head at the North end of Campobello Island at 44° 57' 36" N 66° 52' 48"W. Foul weather and sea conditions may affect boarding time. A 24-hour estimated time of arrival is requested. • Eastport is approximately 10 miles from the pilot station. • Quoddy Pilots, USA 207-263-6403. • Eastport Pilots USA 207-853-6020.
Turning Basins	Not applicable in Eastport.

Port Fees	
Fee Structure	• \$3.00 per-foot per-day. • \$10.00 per-passenger. • Full security services: Up to \$75 per hour for port security officers.

Maps

