

## **Digital Clamp-on Meter**

## 1000A AC Amp + 2000MΩ

Model: DCM 2600

## Features:

- 3 1/2 digit display
- AC current up to 1000A
- AC voltage up to 750V
- DC voltage up to 1000V
- Resistance up to 2000M Ohm
- Audible continuity test
- Over range indication
- Maximum recording mode
- Confirm to the IEC-1010-1 UI1244/UL3111, CE standard
- Hand guard protection Model: DCM 2600
- Carrying case Click here for larger image

## **Specifications:**

DC Voltage Ranges: 1000V,±(0.5%+1dgt)

AC Voltage Ranges:

750V,±(1.2%+4dgts) AC Current Ranges:

200A,1000A,±(1.5%+5dgts)

Resistance Ranges:

 $200\Omega$ ,  $20k\Omega$ ,  $20M\Omega$ ,  $2000M\Omega$ ,  $\pm(1\%+3dgts)$ 

Continuity Test:

Audible indication  $200\Omega$ , Threshold <  $75\Omega$ 

General

Power Requirement: One 9V battery

Dimensions:

10.8"x3.6"x1.7" (275x90x43mm)

Weight:

17 oz(482g) Accessories: Test leads, soft carrying case, battery, and owners manual