

S/N	WORK DESCRIPTION	THREATS	WHO MIGHT BE HARMED OR EXPOSED	CONSEQUENCES	CONTROL OF HAZARDS	RECOVERY
21-A	DISMANTLING OF CONTROL/ DISTRIBUTION SYSTEM OF ELECTRICAL PANEL.	- Starting work Without approval. - Commencement of task without conducting J.H.A. - Executing task without dedicated competent/ supervisory team. - Dismantling without relevant isolation. - Dismantling without relevant caution signs. - Working without protective Devices. - Use of wrong tools - Absence of lifting facility. - Failure to isolate.	Electrical crew, other crew, facility and work tools.	- Fire out break - Damage to work tools. - Damage to facility/equipment. - Injury to personnel. - Object falling.	- Obtain PTW before task exception. - Conduct JHA before commencement of job. - Use safe and right tools. - Safe check tools before use. - Engage only competent personnel. - Keep environment clean and tidy. - keep off unauthorised personnel. - Provide safe and approved lifting device. - Use relevant PPE - Observe dismantling procedures.	Provide protection equipment, first aid kits, communication system and medivac.

S/N	WORK DESCRIPTION	THREATS	WHO MIGHT BE HARMED OR EXPOSED	CONSEQUENCES	CONTROL OF HARDS	RECOVERY
22-A	SERVICE/REPAIRS OF CONTROL/DISTRIBUTION SYSTEM OF ELECTRICAL PANEL.	- Starting task without approval. - Commencement of task without conducting J.H.A. - Executing task without dedicated, competent/supervisory personnel. - Carrying out repairs without appropriate warning signs. - Working without P.P.Es. - Use of wrong tools. - Poor work organisation. - Non-observance of service procedures.	Electrical crew, other crew, equipment and facility.	- Injury to personnel - Damage to work tools, equipment and facility. - Electrocution - Use of wrong tools - Not isolating from power source.	- Obtain PTW before task execution. - Conduct J.H.A before commencement of task. - Use safe and right tools. - Engage the services of only qualified and competent personnel. - Use relevant PPEs - Display relevant caution signs. - Follow repairs procedures.	Provide fire protection equipment. First and resources, effective communication and medivac.
22-B	INSTALLATION OF CONTROL/DISTRIBUTION SYSTEM OF ELECTRICAL PANEL.	- Starting task without approval. - Commencement of task without conducting J.H.A. - Executing task without dedicated/competent supervisory team. - Working without relevant P.P.E. - Use of wrong and unsafe tools. - Absence of relevant caution signs. - Absence of lifting facility.	Electrical Crew, other crew, facility and hand tools	- Falling object. - Use of wrong tools. - Damage to tools. - Over crowded work area. - Injury to personnel.	- Obtain P.T.W. before task execution. - Use safe and right tools. - Conduct J.H.A before work commencement. - Provide competent personnel for task execution. - Provide lifting facility. - Provide relevant caution signs. - Follow relevant installation procedures - Keep environment clean and tidy. - Use relevant P.P.E. - Keep unauthorised personnel.	Provide first aid resources, fire protection equipment, effective communication and medivac.