

Repairs at 835 Windsail Nov 2023

<https://docs.google.com/document/d/1TPu3LESMevaKxAdjMjkNNFGACkdVmei1VZkTJ-hlco/edit?usp=sharing>

Nov 3, 2023

Property: 835 Windsail Ln, Stockton, CA 95206

Tenant: Irene Bob 2022 at 835 Windsail (209) 326-5491 • mobile

- 835 Windsail repair list
- 1) bathroom floor water damage;
- 2) the dishwasher is not working;
- 3) the patio roof is still not fixed; it got ripped off in a wind storm.
- 4) the fire/smoke detector alarm - it's so high tenant can't reach it to change batteries.

Bathroom floor:











End