

30/5 uF Capacitor Replacement for SFCAP30D5440R , 27L20 , CPT-0659 , CPT659 , CPT00659 , TRCFD305 , C4305R , 97F9981 , 97F9833 , 27L877 , C3305R , HC98JA031D , PRCD305 , USA2226 , P291-3054R , HCKS300D050R440Z.

35/5 uF Capacitor Replacement for 97F9834 , Z97F9834 , HC98JA036 , P291-3553R , HC98CA036 , HV98CA035 , 97F9834 , R100335-05 , 89M73 , HC98JA036D , TT-CAP-35/5/440R , RC0102 , TRCFD355 , 12283 , Z97F9848 , Z97F9899 , 97F9899 , CAP050350440RS , 12266 , C3355R.

40/5 uF Capacitor Replacement for 97F9838 , Z97F938 , 97F9838BZ3 , 12786 , RC0108 , 97F9849 , C3DR405 , Z97F9848BZ2 , P291-4054RS , C3405R , HCKS400D050R440Z , P291-4053RS , TT-CAP-40/5/440R , TRCFD405 , TP-CAP-40/5/440R , HC98JA041 , HC98CA040 , HC98CA041 , HC93CZ035.

45/5 uF Capacitor Replacement for 97F9895 , Z97F995 , 97F9895BZ3 , 27L880 , TRCD455 , TRCFD455 , PRCFD455 , 27L889 , 97F9851 , 97F9851S , 12788 , RC0114 , Z97F9895 , 97F9895 , TT-CAP-45/5/440R , HC98KA046 , TP-CAP-45/5/440R , CAP050450440RT , HC98JA046 , HCKS450D050R440Z , 00662441180262.

50/5 uF Capacitor Replacement for 97F9850 , 97F9970 , 97F9970BZ3 , TRCFD505 , RC0120 , 12790 , RC0121 , 1094993 , 38514D018 , P2915053R , HC98CA050 , P291-5053RS , 024-25338-000 , 43-25133-25 , P291-5053R , HC98JA051 , 43-23204-15 , 432320415 , 05706036 , D6789043 , B94577400 , B945774-00 , CARG32458 , TT-CAP-50/5/440R , 27L601 , TP-CAP-50/5/440R , HCKS500D050R440Z , B9457-7400.

55/5 uF Capacitor Replacement for P291-5554RS , P291-5553R , TT-CAP-55/5/440 , cap050550440rtp , cap050550440rt , TRCFD555 , 97Z9839BZ3 , Z97F9839 , 97F9839 , 97F9839BX , CPT00670 , P2915554RS , TP-CAP-55/5/440R , HCKS550D050R440Z.