

# Electrical PO 12/19

\*All quantities of items are in the (parentheses) then the name of the tool **bolded** and Underlined

(1) **10 amp 12v fuses**: we have almost run out of these fuses which we need for the PDP

<https://tinyurl.com/44chbkjy>

(1) **20 amp 12v fuses**: we only have one more of these fuses which we need for the PDP

<https://tinyurl.com/2pj8v49h>

(10) **SB50 6 guage connectors**: these will be used on the older batteries chargers since the wiring on those only need a few updates and any extra will likely be used throughout the season (we need these tabs in case we have to do last minute fixes or for some reason assemble battery leads throughout the season)

<https://powerwerx.com/anderson-sb-connectors-sb50-50amp>

(1) **AC to DC converter**: we need this for powering the valve for the t-shirt cannon. I don't know if this has already been ordered but we definitely need it!

<https://tinyurl.com/3nptbm9p>

(2) **Resin Core lead free Solder**: Currently we do not have any resin core or lead free solder. So, this will make soldering not only easier but also less toxic! As we are just finishing up a few of the spools that came with the soldering irons this would be a perfect time to get more!

<https://tinyurl.com/2d8stye3>

(2) **5in fan**: since we are in the office now it does mean there is less air flow and it is not good to have everyone breathing in the fumes without any circulation. These are some small fans that can at least be put next to where the soldering is happening and pull it away from the person soldering plus providing some circulation

<https://tinyurl.com/bdf722h9>

\*All quantities of items are in the (parentheses) then the name of the tool **bolded** and Underlined