http://mullapperiyaar.blogspot.in/ Friday, November 9, 2007

A Trip to Mullaperiyar 1



From Thekkady Boad Landing to Mullaperiyar

Sunday, November 11, 2007




Thekkady Lake



Thekkady Lake

Monday, November 12, 2007



Animals at Thekkady

Tuesday, November 13, 2007



Thekkady Lake Palace

Wednesday, November 14, 2007



Elephants at Thekkady


Thursday, November 15, 2007



Mullaperiayar Spillway. Spilling water is going to Idukki Reservoyer. There are 13 shutters for this spillway. All these shutters are opened all time. Lot of stones are laid to prevent water spillage in front of these spillway.



Elephants at the reserve forest.



Saturday, November 17, 2007



Main dam and spillway



Main Dam

Saturday, November 17, 2007



Closer look to the main dam




Main Dam view from inside




Boat and the dam.

Wednesday, November 28, 2007




Boats at the dam

Sunday, December 2, 2007




J Benny Cook.

Monday, December 3, 2007




Face of the Dam. Kerala police is doing security duty here.



Foundation stone. Laid on 1895.

Thursday, December 13, 2007







Dam from the top




Back side of the Dam.



Walkway over the dam.

Saturday, December 15, 2007



Photos from the top of the dam.



Cable anchoring done by Tamilnadu in 1979.



Evening over the dam.




Periar Tiger Reserve. Sepege water is going this way.



Animals in the Reserve

Sunday, December 23, 2007


മുല്ലപ്പെരിയാറിലേയ്ക്കൊരു യാത്ര - 15



Sketch of the Dam. Baby dam is built later without official sanction.




Top of the sand dam between baby dam and main dam.



Top of the Baby dam. This is the most weak part in Mullaperiyar Dam.



Back side of Baby Dam.




Elephants at Baby Dam.

Thursday, December 27, 2007



Way to the gallery.




Gate Locked for kerala.



Inside view of gallery. There is not enough oxigen to breath inside this gallery.



These cracks are due to the aeging of the Dam.



Swepage water is going through this small path. -യാത്ര തുടരുന്നു...



Mullaperiyar dam at 115 Feet. What about the cracks.



Cracks to the main wall.



Cracks on the main wall. and the water is entering into the dam.



Cracks Cracks on the wall...



The plaster is gone. Only stones leave. A dam on Bare Stones.




Cracks betwen the stones.







No Plasters in between the stones.



Vandiperiyar Town.





Idukki Dam on a rainy season. If Idukki dam break the water will raise on the fifth floor of High court building Ernakulam.



High court building at Ernakulam




Photo : Nicholas & Co., Madras.

