





Republic of the Philippines
Department of Education
Region VII, Central Visayas
DIVISION OF LAPU-LAPU CITY
Marigondon National High School
Marigondon, Lapu-Lapu City

School Year 2020-2021

# BRIGADA ESKWELA PHYSICAL FACILITIES AND MAINTENANCE NEEDS ASSESSMENT FORM

Instruction: Conduct an ocular inspection of the school physical listed below. Then provide the needed information to facilitate the improvement to be done on these identified facilities. (If needed you may use separate forms for each classroom or school facility).

FACILITIES	CONDITION (Check One)		Remarks	Nature of improvement	Material Resources	Manpower Needed(Indicate
	Satisfactor y	Unsatisfactor y	If Unsatisfactory, describe the problem	Needed (e.g. repair, repainting, replacement, etc)	Needed (Indicate kind and quality)	quantity and nature of labor services needed)
<ul> <li>Washing area /stations / facilities</li> </ul>	V		Needs maintenance - Soap for disinfection - Clogged sink - Flowing water	- Maintenance - Monitoring - Cleansing	<ul><li>Soaps</li><li>Disinfectants</li><li>Regular flowing water</li></ul>	Ordinary labor
Water Pumps	V		Needs maintenance	Needs regular check-up for full operations	- Roof Cover	- Plumer - Carpenter
Drainage system		V	Needs repair: drainage systems need cover while some areas are no longer useful due to clogged soil,	- Repair - Cleaning	<ul> <li>Angle bars</li> <li>Flat bars</li> <li>Welding machine</li> <li>Welding rods</li> <li>Paint</li> </ul>	- Welders - Painters - Cleaners







#### DIVISION OF LAPU-LAPU CITY

## Marigondon National High School

			rock and other forms of debris.			
Washing area/stations /facilities	V		Needs maintenance - Soap for disinfection - Clogged sink - Flowing water	- Maintenance - Monitoring - Cleansing	- Soaps - Disinfectants Regular flowing water	Ordinary labor
Water Pumps	V		Needs maintenance	Needs regular check-up for full operations	- Roof Cover	- Plumer - Carpenter
Drainage system		V	Needs repair: drainage systems need cover while some areas are no longer useful due to clogged soil, rock and other forms of debris.	- Repair - Cleaning	<ul> <li>Angle bars</li> <li>Flat bars</li> <li>Welding     machine</li> <li>Welding rods</li> <li>Paint</li> </ul>	- Welders - Painters - Cleaners
Roofs and gutters of classrooms, hallways, and offices	V		Needs minor repair	- Cleaning - Repainting	- Paint - Broomsticks	- Carpenter Ordinary labor







## DIVISION OF LAPU-LAPU CITY

## Marigondon National High School

			- Clogged gutter ed leaves on the		- Scrapes	
Ceilings of classrooms and laboratories	V	Nee	eds minor repair Dirty ceiling htly detached ing walls	- Repair - Repaint	- Paint - Plywood - Nails	- Carpenter - Labor
Outer and inner wall of school building	V	Nee	eds cleaning - Cracked paints - Faded out paints	- Repainting	- Paint - Paint brush Paint remover	- Painter - Labor
<ul> <li>School landscaping,</li> <li>Greening and School</li> <li>Grounds</li> </ul>	<b>&gt;</b>		ntenance - Watering of plants - Removal of weeds noval of dried	- Maintenance - Additional plants	- Flowing water	Ordinary labor
Lighting system	V		eds minor repair - Hanging wires	- Replacement - Rewiring Reconnection	<ul><li>New bulbs</li><li>New lamp</li><li>holders</li></ul>	- Electricians - Carpenters - Labor







## DIVISION OF LAPU-LAPU CITY

## Marigondon National High School

			- Loose connection Busted lamps		- Wires Woods	
Classroom windows, doors, and blackboard	V		Needs minor repair	- Replacement - Repair	- Window blades - Doorknobs Window frames	- Carpenter - Labor
Classroom furniture		<b>&gt;</b>	Some classrooms doesn't have enough chairs - Broken chair Table stands	- Additional chairs - Repair Repaint	- Chairs - Paint - Woods - Nails - Adhesives	- Carpenter - Labor
School Comfort room		<b>&gt;</b>	Needs repair and maintenance - Broken doors Clogged bowls	- Repair - Repainting Cleaning	- Paint - Woods - Nails Cleaning materials	- Plumber - Carpenter - Labor
Water system	<b>~</b>		Needs minor repair - Faucet	Additional faucet	- Pipes - Faucets Adhesives	Plumber
School perimeter fence	V		Needs minor repair - Vertical bars	- Repair Repainting	- Paint - Angle bar - Square bar Round bar	- Welder - Labor







## DIVISION OF LAPU-LAPU CITY

Marigondon National High School

			- Horizontal bars - Angle bars			
DRRM signages  • Evacuation plan	<b>✓</b>		Needs more visual - Exit point - Entry point Location maps	- Repair - Replacement - Additional	- Printed maps - Printer entry signs - Printer exit signs School maps	- Layout maker Labor
Installation of teachers and learners' hub	<b>\</b>	<b>&gt;</b>	Needs construction - Facility - Structure Location	- Construction	Construction materials	- Carpenter - Labor
Unserviceable furniture's and fixtures		V	Piled up unserviceable chairs and construction materials	Relocation of unserviceable chairs and construction materials	- Storage area - Storage room	- Labor
School stage/covered court		<b>~</b>	Needs repair and repainting - Roof painting Benches painting	- Repainting - Welding - Cleaning	- Paint - Welding rods Angel bars	- Welder - Labor - Painter
Maintenance of school tools and equipment	<b>~</b>		Needs inventory	Recking of inventory	Storage area	- Labor







Republic of the Philippines Department of Education Region VII, Central Visayas DIVISION OF LAPU-LAPU CITY **Marigondon National High School** Marigondon, Lapu-Lapu City School Year 2020-2021

Prepared by:

Noted by:

**JOSE LERRY MEDIANA** 

School Physical Facilities Coordinator

February 10, 2021

Date of Inspection

LINA M. MAISO Principal II, SHS

DEGOLLACION

Secondary School Principal IV

CIRILA B.