

1. Site: Marshall Run, Fulks Run, VA
2. Prioritization of healthy watersheds for protection
3. Blizzard of 1996
4. Culvert replaced
5. Characteristics of impassable culverts
6. Root causes of culvert failure
7. Brook trout life cycle, complementary habitats, and migrations
8. Prevalence and effects of impassable culverts
9. Solution:
 - a. update VDOT's standards to meet fish-passage requirements
 - b. expand VDGIF fish-passage program
 - c. Increase funding