


Monthly Engineer Report

(ALAS HARUM BALI GROUP)
FOR THE MONTH OF JANUARY
2026




Engineering Project

Date	Areas	Before	After
01 Januari 2026 Thursday	Penggantian fitting dan lampu obor depan goa gorila		
	Perbaikan tutup tangki toilet bowl di loby		

	Pemotong dan pemasangan plat bordes coolroom di fastry		 A photograph showing the interior of a coolroom. On the left, there is a green plastic crate. The floor is made of metal plates with a diamond pattern. In the background, there are shelves with some containers. The photo is taken with a Redmi Note 13 5G on 01/01/2026 at 12:31.
	Penyambungan kembali kabel lampu sorot di Transit flying fox		 A photograph showing a person in green clothing working on a cable for a spotlight. The person is using a tool to connect the cable. The scene is outdoors, with trees and foliage in the background. The photo is taken with a Redmi Note 13 5G on 01/01/2026.
	Penyambungan kabel lampu sorot di pohon kelapa bed swing		 A photograph showing a spotlight cable connected to a tree. The cable is running along the trunk of the tree. The scene is outdoors, with trees and foliage in the background. The photo is taken with a Redmi Note 13 5G on 01/01/2026.

Vlas Harum

Bali

	Pergantian 1 bal Valve inget pool Sadewa	 realme C75 1 Januari 2025 pukul 18:13
	Cleaning Filter Ac SS	 2026/01/01 19:11
	Pembongkaran lampu pohon natal di lobby	 2026/01/01 19:18


Vilas Harum

Bali

	pergantian banner		
	pemasangan kain di food pass		
	Perbaikan plampung toilet Bowl Arjuna		

Vlas Harum

Bali

	Repaint Pintu Cowboy Lobby		
	Pemotongan rak sepatu di drupadi done		
	Pergantian saklar lampu di drupadi		


Vlas Harum

Bali

	Pengelasan Railing coffee explane		
02 Januari 2025 Friday	Pemindahan kipas di Yudis		
	Takeout lampu sorot di green wall sadewa		

Vlas Harum

Bali

	pergantian jet spre toilet bar sadewa		 REDMI 13X ENG AHB 02/01/2026 10:51
	Perbaiki dan keringkan saklar yg basah dan nyetrum di lobby		 realme C75 2 Januari 2026 pukul 19:09
	Pengecatan 9 kursi di meting room karna		 realme C75 2 Januari 2026 pukul 21:26


Vilas Harum

Bali

	Perbaikan listrik yang mati di accounting		 A photograph of an electrical panel with several circuit breakers and wires. The timestamp at the bottom left is 2026/01/02 23:51.
	Perbaikan mampet pembuangan limbah kitchen di cretya sunset		 A close-up photograph of a clogged drain pipe in a kitchen sink. The timestamp at the bottom left is 2026/01/02 20:52.
03 January 2025\ Saturday	Pergantian lampu sorot di finish flying fox		 A photograph showing a hand holding a smartphone to take a photo of a flying fox structure. The timestamp at the bottom right is 03/01/2026 08:10.
	Pergantian braket lampu par di pekak brayut		 A photograph showing a hand holding a wrench and a screwdriver next to a light fixture. The timestamp at the bottom right is 03/01/2026 08:10.


Vilas Harum

Bali

	Pergantian lampu obor di area finish flying fox		
	Pergantian lampu obor di jembatan pekak brayut		
	Pemasangan atap di box panel dibawah jembatan kak Brayut		


Vilas Harum

Bali

	Pergantian MCB dan perbaikan cover duradus di bwh jembatan gantung sisi timur		
	Pergantian MCB dan perbaikan cover duradus di bwh jembatan gantung sisi barat		
	pemindahan lampu penjor ke sign exit		

Vilas Harum

Bali

	Pemasangan 3 kipas angin di cretya jungle		 A person is using a ladder to install fans on a thatched roof. The roof is made of woven palm leaves. The person is wearing a dark shirt and pants. The ladder is a wooden A-frame ladder. The fans are black and white. The photo is taken from a low angle, looking up at the person and the roof. The text 'REDMI Note 13 5G' and '03/01/2026 21:40' is visible in the bottom left corner.
	Pemasangan sign yang lepas di patway barong luwak		 A person is holding a wooden sign. The sign is made of light-colored wood and has some text and a logo on it. The person is wearing a white t-shirt and brown pants. The background shows a stone path and some greenery. The text 'REDMI Note 13 5G' and '03/01/2026 18:35' is visible in the bottom left corner.
	pemasangan ulang undesit yg goyang di tangga kitchen cretya Ubud		 A person is working on a kitchen sink. The person is wearing a black t-shirt and is leaning over the sink. The sink is made of dark material and has some water in it. The background shows a kitchen area with some items on the counter. The photo is taken from a high angle, looking down at the person and the sink.

Vilas Harum

Bali

04 January 2025 Sunday	Pemasangan ulang logo lantana di kabana bawah		 A hand is holding a circular arrangement of yellow and white lantana flowers against a wooden wall. The flowers are arranged in a ring, with yellow petals and white centers. The background is a dark wooden wall. A blue object is visible in the bottom right corner.
	Pergantian trafo lampu striplamp di jembatan gumitir		 A wooden bridge with a power transformer and a string of lights. The bridge is made of dark wood and has a metal railing. A power transformer is visible on the bridge, and a string of lights is hanging from it. The background shows green foliage.
	Penyambungan lampu dan pergantian 2 trafo lampu striplamp di jembatan gantung		 A wooden suspension bridge over a river. The bridge is made of dark wood and has a metal railing. The background shows green foliage and a river.

Vlas Harum

Bali

Pergantian lampu obor
di barat sungai



Perbaikan cover
tungku pizza yang
kurang rapat sekaligus
cleaning



	Pemotongan pipa pembuangan wastafel meeting room agar air kotor wastafel lebih lancar		
	Pergantian accu genset		
	Pergantian lampu obor di cabana bawah		


Vlas Harum

Bali

pergantian saklar di
srikandi



Pengelasan di patway
gumitir





pergantian lampu par
di gorilla



Vlas Harum

Bali

	perbaikan undesit yg lepas di swing		
	Pergantian keramik di toilet srikandi		
	Perbaikan kran di produksi		

Vlas Harum

Bali

	Penyemenan jalan di lobby		
05 Janurary 2026 Monday	Kancip ulang sofa di lobby		



Vlas Harum

Bali

	pergantian lampu di shower room nakula		
	Pergantian 2lampu obor di pathway barat		
	Perakitan pompa sumersible di ganesha		




Vlas Harum

Bali

	Penyecrupan ulang di omah kayu		
	Perbaikan mampet di shower room drupadi		
	Pemindahan besi dari parkiran ke ws		


Vlas Harum


Bali

	Penambalan pelafon di srikandi		 A person is standing on a ladder, working on a ceiling. The ceiling appears to be made of a light-colored material, possibly plaster or drywall, and there is a bright light source visible in the upper left corner of the frame. The person is wearing dark clothing and is focused on their work.
	Pengecatan tiang extantion		 The image shows a workshop or storage area. There are various tools, equipment, and materials visible. A person is standing in the background, and the overall environment appears to be a workspace for maintenance or construction work.
	Pemasangan ulang anti slip di tangga jakuzi sadewa		 A close-up view of a staircase. The steps are covered with a dark, textured material, likely anti-slip tape or paint. The metal railings of the staircase are visible on the left side of the frame.

Vlas Harum



Bali

06 January 2026 Tuesday	Perbaiki batu di timur cretya lite		
	perbaiki handle pintu di accounting		
	Perbaiki engsel pintu loker 03 di drupadi		

	Pengelasan besi tangga menuju omah kayu		
	Pengelasan cincin railing tangga omah kayu		
	Pengelasan 5 cincin kursi di bwh karna lounge		
	Penambahan akrilik pada talang air di bima		


Vlas Harum

Bali

	Pengecat besi raka meja kasir Drupadi		
	Pengecatan railing di cretya lite		
	pemasangan akrelik di atap bima		
07 January 2026 Wednesday	Pergantian lampu obor di pathway barat		



Vlas Harum

Bali

	penyambungan pipa air sawah di sungai		
	perapian pipa dan puing” di yudis		
	Pergantian kunci di loker cewek dan cowok		



Vlas Harum

Bali

	Pergantian batu andesit di area kandang luak		 realme C75 7 Januari 2025 pukul 20:03
	Pergantian lampu yg mati di bwh karna lounge		 realme C75 7 Januari 2025 pukul 20:09
	Pemasangan ulang batu andesit di tangga menuju singgel enjel swing		 realme C75 7 Januari 2025 pukul 20:16

Vilas Harum

Bali

	Penambahan bantalan wodenfloor yudist		 A person wearing a green shirt is kneeling on a dark wooden floor, working on it. There are some tools and a small container nearby. The image is taken from a high angle. Metadata: Shot on realme 8 5G, 2026 01 07 20:51
	Pengecat kursi di bawah srikandi		 A metal chair is on a stone patio. There are some plants and a wall in the background. The image is taken from a low angle. Metadata: 07/01/2026 20:45
	Pergantian lampu jungle		 A person is standing in a jungle setting, reaching up to change a light bulb. There are many plants and a thatched roof in the background. The image is taken from a low angle. Metadata: XIAOMI 11T PRO, 07/01/2026 20:48

Vilas Harum

Bali

08/01/2026 Thursday	Pengacipan ulang sopa di cretya lite		 REDMI 13X ENG AHB 08/01/2026 07:55
	Pergantian lampu obor di barat sungai		 REDMI 13X ENG AHB 08/01/2026 10:00
	Pergantian lampu obor dan fitting di jembatan anyaman		 REDMI Note 13 5G 08/01/2026 10:11
	Pengyekurupan 2 wooden flor yang terlepa di gumitir		 REDMI Note 13 5G 08/01/2026 10:31

Vlas Harum

Bali

	Perbaikan pilot api yang mampet di cretya lite		 REDMI Note 13 5G 08/01/2026 10:55
	Cleaning area ws		 REDMI 13 5G ENG AHB 08/01/2026 11:26
	Pergantian LPG kitchen cretya ubud		 2026/01/08 16:37

Vilas Harum

Bali

	Pergantian hand shower di toilet driver		
	Perbaikan chiller yang nyetrum di bar yudist		
	Penambahan cincin kursi di cretya lite A		
	Pergantian lampion di cretya lite B		



Vlas Harum

Bali

09 January 2026 Friday	Pergantian lampu sorot di entrance Yudis		 realme C75 9 Januari 2026 pukul 10:15
	Perbaikan cover lambu di teras bima tangga menuju Arjuna		 realme C75 9 Januari 2026 pukul 08:59
	Perbaiki pilot oven di pastry yg tdk mau hidup		 realme C75 9 Januari 2026 pukul 08:39

Vilas Harum

Bali

	Perbaikan 2 kunci shower room Nakula yg longgar		
	Perbaikan engsel sign maintenance yg lepas		
	Pergantian fitting lampu obor di barat sungai		

Vilas Harum

Bali


Pergantian fitting dan lampu obor di tangga depan sarang burung bulat



Pemasangan 5 akrilik standar grooming



pemotongan untuk perapian besi bekas




Vlas Harum

Bali

Reposisi dan penambahan sekrup 5 kipas angin di dress omah kayu




Pemasangan ulang tangan patung yang lepas di omah kayu





Vlas Harum

Bali

	Perbaikan wastafel mampet di kantin		 A person wearing a blue and gold batik shirt is standing at a white sink. They are using a long, thin metal wire to clear a clog in the drain. The sink is set into a white countertop. A yellow bottle of dish soap is on the counter next to the sink. The background shows a tiled wall and a sign that says 'DILARANG KEMUKAAN DARI'.
	Penambahan kabel dan pencarian short di dress		 A view looking up at a ceiling with exposed wooden beams. A single light fixture is hanging from the ceiling, casting a warm glow. The ceiling is made of woven bamboo or similar material. The walls are dark, and there are some pipes or conduits visible.
10 January 2026 Saturday	Pengecekan gas bocor kitchen cretya ubud		 A row of red gas cylinders (propane tanks) in a kitchen area. The cylinders are stacked and have red handles. Some have labels like 'BP-1'. The background shows a wooden wall and some greenery outside.

Vlas Harum

Bali

	Perbaikan lampu di Srikandi		
	Penyekrupan ulang di jembatan menuju omah kayu		
	Pergantian wooden floor di Terrance bima		

Vilas Harum

Bali

	Pergantian engsel pintu cowboy di lobby		 2026/01/10 12:29
	Penginstalan 2 lampu di dress omah kayu		 2026/01/10 12:38
	Perbaikan 5 kain sofa di cretya lite C		 2026/01/10 13:04
	Pergantian lampu di bima		 Shot on realme 8 5G 2026/01/10 16:55


Vlas Harum

Bali

Pergantian lampu di
groundtank



Pemasangan ulang
akrilik lampu lantana
di cabana




Perbaikan lampu mati
di Srikandi



Vlas Harum


Bali

	Pemasangan lampu di omah kayu		
	pergantian anti slip di tangga menuju sadewa		

Vilas Harum

Bali



	pergantian anti slip di tangga menuju teras bima		
11 January 2026 Sunday	Pengecatan duckting exhous di atas pastry		
	Repaint sign shower room		

	pengecatan gantungan harnes		
	pergantian kran di preperation bar		
	Pemasangan tre di toilet Srikandi		

	Pengelasan drawer di kitchen cretya lite		 2026/01/11 19:59
	Pemasangan dinding di dress room omah kayu		 2026/01/11 21:01
	Penutupan fentilasi di dress room		 2026/01/11 22:19
	pergantian mechanic toilet urinoir di lobby		 2026/01/11 22:19


Vilas Harum

Bali

	pergantian kayu di cabana atas		
12 Januari 2026 Monday	Pergantian fitting+lampu obor di depan Goa Gorilla		
	Pemasangan Floating Tray Di drupadi		

Vilas Harum

Bali

	Pergantian 2 tali kursi di cretya lite D		 2026/01/12 10:55
	Pengelasan pintu ruang hk di lantai kaca		 2026/01/12 18:15
	pemasangan sign shower di nakula		

Vilas Harum

Bali

13 January 2026 Tuesday	Pergantian lampu obor di goa gorilla		
	Perbaikan Wastafel Bar Cretya Lite Mampet		
	Pemasangan ulang sign yang lepas di nakula		


Vlas Harum

Bali

	Pemasangan dan pengecatan tatakan AC di omah kayu		
14 January 206 Wednesday	Kancip sofa loby		
	Sekrup wooden floor nakula		


Vlas Harum

Bali

	Pergantian lampu par di dekat sarang burung bulat barat sungai		
	pergantian tali di sofa ss		
	pencarian short di lite D		

Vlas Harum

Bali

	Pergantian 1 Tabung Gas di kitchen production	
	Pergantian 15 kunci loker cewek	
	Perbaiki pintu sliding bar kopi	

Vlas Harum

Bali

	MCB cretya lite D trip karna stop kontak di belakang meja kasir cretya lite D kabel bocor		
15 January 2026 Thursday	Pengyekurupan wooden floor di day bed Nakula		
	Pergantian stop kontak di tandon loker		



Vlas Harum

Bali

	Pengyekurupan wooden floor yg goyang di Sahadewa		
	Pergantian lampu mr16 di jalan menuju meeting room		
	Pergantian cover lamp wall entrance cretya pecah (done)		
	Perbaikan strip lamp di gumitir		



Vlas Harum

Bali

	perbaikan wooden wall di bar kopi		
	pergantian lampu di locker cewek		
	Penyedotan septic tank di bwh lantai kaca		

Vilas Harum

Bali

	Pemasangan Bender di kandang luak		
	Perbaiki fitting lampu di ot		
	Perbaiki kabel terbakar di plester bok dekat out gate lobby		


Vilas Harum




Bali

16 January 2026 Friday	Pergantian lampu di loker cowok		 A hand holding a light bulb in a locker room. The room has yellow walls and wooden lockers. A mirror is visible in the background. realme C75 16 Januari 2026 pukul 07:05
	Pengelasan Rell certain di kabana bawah		 A man wearing a green shirt and sunglasses is welding a metal frame outdoors. There are palm trees and a blue sky in the background. realme C75 16 Januari 2026 pukul 07:49
	Perbaikan tali kre yang lepas di srikandi		 A close-up shot of a rope being fixed or repaired. The background shows green foliage and a bright sky.

Vlas Harum


Bali

	Pencarian jalur short di area pertigaan flying fox		
	Pemblodengan kabel di exit		
	Pemasangan ulang batu di pathway barat		

	Penanaman kabel di depan sarang burung Jembatan anyaman		
	Pemblodengan jalur kabel di pathway barat		
	Pergantian antiselip menuju nakula		
	Pergantian lampu pool Sadewa		



Vilas Harum

Bali

17 January 2026 Saturday	Cleaning ws	 realme C75 17 Januari 2026 pukul 07:01	 realme C75 17 Januari 2026 pukul 07:22
	Pengelasan pintu di bar jungle lite		 realme C75 17 Januari 2026 pukul 07:55
	Pergantian lampu obor di barat sungai		 realme C75 17 Januari 2026 pukul 09:35


Vilas Harum

Bali

	Perapian kabel di patung luwak sebelah utara		 realme C75 17 Januari 2025 pukul 13.10
	Penanaman jalur kabel di gumitir dan finish playing fox	 2026/01/17 17:02	 2026/01/17 17:20
	Pergantian 2 lampu lampion di lite D		 2026/01/17 21:51



Vlas Harum

Bali

	Pergantian lampu di susuk		
	Pergantian Strip Lamp yg Mati Di Jembatan Gumitir		
	Pemasangan Kaca Mading		
	Pemasangan ulang antiselip di tangga menuju nakula		


Vlas Harum

Bali

	Pergantian antiselip di tangga menuju drupadi		
	Pemasangan andesit yg lepas di roasting area		
	Pengelasan besi showing proses pembuatan luwak kopi		
	Pengelasan gutter bawah goa anyaman		


Vlas Harum

Bali

18 January 2026 Sunday	Pergantian fitting+lampu obor di jembatan ganesha		
	Pergantian 4 downlight di goa menuju ganesha		
	Pergantian 3 fitting dan lampu obor di tangga menuju ganesha		
	Pergantian 7 lpg kitchen Cretya Ubud		

Vlas Harum

Bali

	Perbaikan 3 cutleris		
	General cleaning ws		
	Perbaikan lampu downlight goa ganesha		
	Cleaning ac di production		


Vlas Harum

Bali

	Pengecoran dan pemotongan kaki tong security		
	Pergantian seling omah kayu		
	Pengelasan cincin reling depan kasir omah kayu		


Vilas Harum

Bali

19 January 2026 Monday	Pergantian lampu di side stand inside bima		
	Pergantian gas LPG 50 kg. Total 3 tab di kitchen production		
	Pergantian wooden di Bar nakula		
	Pergantian lampu par Pekak berayut		


Vlas Harum

Bali

	Pergantian selang plexible zink Bar cretya Lite		
	Pergantian fitting dan lampu obor di jembatan menuju peka brayut		
	Pergantian fitting dan lampu obor di tangga menuju ganesha		
	Penambahan kawat di jalur waterfall selatan		


Vlas Harum

Bali

	Pergantian lampu di back office		
	Penggantian wooden floor di couple bike		
	Pemasangan terpal untuk atap di bar kopi		
	Pemasangan batu di jabatan anyaman		



Vlas Harum

Bali

	Pemasangan 2 bantu yg lepas di depan barong luwak		
	Perbaikan tangga di pathway gumitir		
	Pemasangan antiselip di tangga menuju drupadi		


Vilas Harum

Bali

	Pergantian lampu pool drupadi		
	Pergantian 3 lampion lite C		
20 January 2026 Tuesday	Perbaikan music yang mati		




Vilas Harum

Bali

	Penginstalan air untuk tim hk		
	Pergantian 2 fitting dan lampu obor di goa gorilla		
	Pergantian striplamp yang terbakar area pathway gunitir		
	Pergantian travo dan striplamp yang terbakar di jembatan gantung sebelah utara		


Vlas Harum

Bali

	pergantian lampu di bar coffee		
	Pergantian lampu lampion di lite c		
	Pergantian lampion di late c		



Vlas Harum

Bali

	Pengelasan drip Santa di kitchen lite		
21 January 2026 Wednesday	Pergantian lampu di toilet lobby		
	Pergantian fitting dan lampu obor pathway barong luwak		

Vlas Harum


Bali

	Pergantian lampu downlight goa anyaman		
	Pemasangan keran di topeng monyer		
	Perbaikan kabel shot di bawah patung luwak		

	penambalan pembuangan exos kitchen cretya ubud		
	Pengcoran lantai andesit yg jebol di depan roasting		
	Pengecatan triplex penutup rangka Meja Bar Yudis		


Vlas Harum

Bali

	pergantian 2 lampu di back office		
	Cleaning Ac 3unit di Back Office		
	Penarikan Kabel Stop Contak 4titik di Bar yudis		



Vlas Harum

Bali

	Pemasangan kayu Panel di yudis		
22 January 2026 Thursday	Pemasangan anti slip di tangga menuju Nakula		
	pemasangan gas kitchen cretya ubud		
	pergantian lampu di exos kitchen cretya ubud		




Vlas Harum

Bali

	Pergantian kunci loker cowok (continue terpasang 17 pcs sisa lagi 14 pcs)		
	Perbaikan cover lampu di toilet Srikandi yg lepas		
	Pemasangan Guter bar Yudis		


Vilas Harum

Bali

	Pengecatan dinding Bagian Belakang Bar yudis		
	Pemasangan ulang anti slip Jakuzi Atas		
	Pemasangan ulang Anti slip tangga menuju nakula		
	Pemindahan kipas dari dress omah kayu ke store lobby		


Vlas Harum

Bali

	Pergantian kabel dan lampu di waterfall		 realme C75 22 Januari 2026 pukul 22:25
23 January 2026 Friday	pengelasan cicin di teras arjuna		
	Pergantian Triplek Cabana 38		 2026/01/23 09:10

Vlas Harum

Bali

	Penambahan Bantalan Wooden Dack Yudis	 2026/01/23 09:46	 2026/01/23 09:54
	Pergantian Lampu obor di pathway topeng monyer		 2026/01/23 12:13
	pengecekan ac netes di office agro		


Vlas Harum

Bali

	Pergantian lampu lampion di dekat table 217 arjuna		 A hand holds a light bulb with a yellow filament. In the background, a lit lantern with a metal frame and a wooden base is visible. The lantern has two circular decorative cutouts at the top. The scene is dimly lit, with the lantern providing the main light source. A timestamp '2026/01/23 21:50' is visible in the bottom right corner of the image.
	Pengecatan Tembok dibawah srikandi		 A white wall is shown, with a green metal railing in the foreground. A plant with long, thin leaves is hanging from the railing. The wall appears to be part of an outdoor or semi-outdoor structure. A timestamp '2026/01/23 22:44' is visible in the bottom right corner of the image.
	Pergantian tatakan sofa di bawah karna lounge		 A blue sofa is shown, covered with a white, textured material. The sofa is positioned on a wooden floor. A timestamp '2026/01/23 23:09' is visible in the bottom left corner of the image.




Vlas Harum

Bali

24 Januari 2026 Saturday	Pergantian travo Strip Lamp depan luwak		
	Pergantian 1 Lampu obor di pathway topeng monyer		
	Perbaikan pintu tps		


Vlas Harum

Bali

	Perbaikan+Repaint 6Cateleris		
	Perbaikan portal ganesha		
	Pemasangan breket jet shower		

Vilas Harum

Bali

	Pergantian jet shower toilet arjuna		
	Pemasangan antiselip di tangga menuju sadewa		
25 Januari 2026 Sunday	Pemasangan ulang tiang lampu obor yg lepas di dekat jembatan kak Brayut		


Vlas Harum

Bali

	Penyambungan kabel speaker dan subwoofer di yudist		 A person in a black shirt and pants is standing on a counter, working on the ceiling area of a room with wooden shelves and a thatched roof. The person is holding a cable. The room has wooden shelves with various bottles and a thatched roof. The person is wearing a black shirt with a logo and black pants. The counter is made of wood. The background shows a view of greenery outside.
	Pemasangan cover kipas angin susuk		 A hand is holding a green and yellow screwdriver, working on the cover of a black electric fan. The fan is a large, black, circular fan with a metal grille. The hand is holding the screwdriver and is in the process of removing or installing a cover. The background shows a room with wooden furniture and a window.
	Perbaikan mampet di wastafel kantin locker		 A hand is using a wire brush to clean a dark, rectangular sink. The sink is made of a dark material, possibly stone or metal, and has a drain. The hand is holding the wire brush and is scrubbing the surface of the sink. The background shows a white wall and a faucet.

Wlas Harum

Bali

	Pergantian handle dan mechanical pintu di ruang cctv		
26 Januari 2026 Monday	Penginstalan 3 stopkontak di back office		
	Pergantian beberapa anti selip di tangga menuju srikandi		
	Pemasangan air curtain di cold room pastry		
	Pergantian pengunci drawer di arjuna		

Vilas Harum

Bali

27 Januari 2026 thuesday	Pergantian lampu obor sebelah sungai samping jembatan anyaman		 REDMI Note 13 5G 27/01/2026 08:55
	Penambahan Mat di tangga jakuzy Sadewa		 2026/01/27 09:11
	Pemasangan Stop Contak di Ticket booth FDC		 2026/01/27 09:46

Vlas Harum

Bali

	Pengecatan ulang cover sampah		 2026/01/27 16:53
	Perbaikan jalur short di peka brayut		 2026/01/27 11:04
	Pergantian 14 kunci loker cowok		 recam Shot on realme 8 5G 2026 01 27 15:45




Vlas Harum

Bali

	Perbaiki handle pintu shower room Nakula yg longgar		 realme C75 27 Januari 2026 pukul 18:37
	Pemasangan foto di training legal		 realme Shot on realme 8 5G 2026 01 27 18:18


Vlas Harum

Bali

	Pergantian 2lampu toilet drupadi		 A hand holds a glowing light bulb in front of a ceiling light fixture. The image is a vertical shot with a black border. At the bottom, there is a small yellow 'realme' logo, the text 'Shot on realme 8 5G', and a timestamp '2026 01 27 19:12'.
	Pengecatan kalsiplank		 A wooden plank is being painted with a brush. The image is a vertical shot with a black border. At the bottom, there is a small white 'realme C75' logo and a timestamp '27 Januari 2026 pukul 17:40'.
	penggantian lampion di lite B		 A person is on a ladder, working on a light fixture. The image is a vertical shot with a black border. At the bottom, there is a small white 'realme C75' logo and a timestamp '27 Januari 2026 pukul 17:40'.


Vilas Harum

Bali

	Penambalan lantai di cretya lite A		 realme C75 27 Januari 2026 pukul 21:28
28 January 2026 Wednesday	Pergantian kayu terace bima		
	Penarikan jalur stop kontak di IT dan UKS		
	Pergantian 1 fitting+ lampu obor di depan goa girilla		 2026/01/26 10:11

Vlas Harum


Bali



	Pergantian lampu di toilet Srikandi		 2026/01/28 14:01
	Pemasangan white board di back office		 realme C75 28 Januari 2026 pukul 16:30
	Pemasangan 5 rekor muri di back office		 realme C75 28 Januari 2026 pukul 16:33

	Pemasangan sign pintu ruangan OM		 realme C75 28 Januari 2026 pukul 15:59
	Pergantian fitting lampu di exhaust kitchen produksi		 2026/01/28 12:51
	Pergantian 2 lampu TL kitchen produksi		 2026/01/28 12:36
	Pergantian lampu pool drupadi		

Vlas Harum

Bali

	pengecatan kusen pintu shower drupadi sebelah selatan		
	penggantian lampu sorot di patung luwak		
29 January 2026 Thursday	Pergantian lampu obor timur sungai		

	Pergantian hand shower toilet loker cewek		 A person is shown from the side, wearing a dark blue shirt and a watch, installing a silver hand shower onto a wall made of large white tiles. The shower head is being attached to a pipe. A timestamp '2026/01/29 12:46' is visible in the bottom right corner.
	Pergantian cover lampu kapal di exit		 A black, oval-shaped light cover is mounted on a wall. The wall is covered in green moss or algae. A timestamp '2026/01/29 13:48' is visible in the bottom left corner.
	pemasangan 3 gas di kitchen prepartation		 Three red gas cylinders are shown in a kitchen. They are connected to a yellow gas line. A timestamp '2026/01/29 13:48' is visible in the bottom left corner.
	Perbaikan senter UV di tiketing cretya ubud yang mati		 A hand is holding a black flashlight with a clear lens. The flashlight is pointed towards the camera. A timestamp '2026/01/29 13:48' is visible in the bottom left corner.

Vlas Harum

Bali

	Pergantian stop kontak dan steker di kitchen cretya lite yang terbakar	 2026/01/29 08:51	 2026/01/29 08:47
	Perbaikan mic di registrasi yang kecil suaranya		 2026/01/29 15:30
	pergantian 6 tissue holder di toilet lantai kaca		
	penggantian 1 lampu obor sebelah jembatan anyaman menuju pekak brayut		



Vilas Harum

Bali

30 January 2026 Friday	Pengelasan rak sepatu yg patah di angel swing		 realme C75 30 Januari 2026 pukul 08:47
	perbaikan lampu di kandang luwak		
	Sekrup kursi srikandi yang lepas		 realme Shot on realme 8 5G 2026-01-30 09:31

Vlas Harum


Bali

	penambahan kabel grounding di bar yudis		
	Perbaiki mampet wastafel bar kopi, tersumbat ampas kopi		
	penggantian 1 lampu downlight di bar jungle lite		

Vlas Harum

Bali


Pergantian pelampung
toilet bowl lobby



pengecatan realing di
bar coffee




Pemasangan 2 akrilik
meja di Nakula




Vilas Harum

Bali

	Pemasangan tali kre di gelato		
	Perbaikan+pemasangan Terpal di deck Nakula		
	Perbaikan kursi area tunggu swing yg Ogal Agil		
31 Desember 2026 Saturday	penambahan 2 sekrup tangga menuju omah kayu		



Vlas Harum

Bali

	perbaikan sign exit yang ocel ocel		
	perbaikan pintu coboy di casir drupadi		
	pembuatan braket lampu HPI untuk di project ghanesa		

Vlas Harum

Bali

	Pemasangan lampu di batang pohon kelapa ganesha		 Kabupaten Gianyar, Bali 2026.01.31 17:55
	Penyekrupan wooden yg ogal agil di lantana	 2026/01/31 17:22	 2026/01/31 17:23
	Penyekrupan atap yg lepas di security check		 Kabupaten Gianyar, Bali 2026.01.31 19:42

[illegible]

PROJECT BY VENDOR

06/01/2026 Tuesday	Monitoring vendor pemasangan dimmer lampu lantana di kabana atas dan bawah		
07/01/2026 Wednesday	Monitoring vendor SDB pergantian modul pematik dan 2 per pintu oven deck di kitchen production		 realme C75 7 Januari 2025 pukul 16:25

Vilas Harum


Bali


	Monitoring vendor SDB maintenance 2 ucc di kitchen cretya Ubud		 realme C75 7 Januari 2025 pukul 21:19
	maintenance stove 4 Burner dan oven di pastry		 realme C75 7 Januari 2026 pukul 21:52
08/01/2026 Thursday	Monitoring vendor maintenance di kitchen cretya lite		 2026/01/08 22:20

Mas Harum

Bali


11/01/2026 Sunday	Monitoring Project Ganesa. Jmlah Pekerja Vendor(3 orang). -Progres Pembuatan Rangka Tapak Ganesha. -Pompa Celup Aman,Berfungsi Normal.		
13/01/2026 Tuesday	monitoring Cleaning Pemanas&Pendingin Kitchen Equipment		

	Monitoring Perbaikan Per Oven Deck Kitchen Production		
16/01/26	Monitoring vendor soil test pengecekan kepadatan tanah untuk perijinan reklame		
17/01/26	Monitoring Vendor project Ganesa untuk melanjutkan pemasangan besi cor		

	Monitoring vendor SDB -perbaikan pilot stove 4 burner -perbaikan oven rational SCC Kitchen cretya ubud	 
18/01/2026 Sunday	Monitoring Vendor Pak Bito Pemasangan kramik bar yudist	 


Vlas Harum

Bali

19/01/26 Sunday	Monitoring Vendor Bestari untuk pembongkaran atap Alang" di bar kopi	 The table contains two photographs documenting the demolition of a thatched roof. The top photograph shows the roof structure being dismantled, with debris visible. The bottom photograph shows two people, one in a brown shirt and one in a black shirt, standing near the roof structure. Both photographs have a timestamp at the bottom: 'realme C75 19 Januari 2026 pukul 23.08' for the top photo and 'realme C75 19 Januari 2026 pukul 19.07' for the bottom photo.
--------------------	--	--

Wlas Harum

Bali

21/01/26 Wednesday	Monitoring vendor pk.bitto. -pengenatan Cramik di Bar Yudis dan pastry	  
-----------------------	---	--

Vilas Harum

Bali

22/01/26 Thursday	Monitoring Vendor penggalian untuk pondasi pathway		
	Monitoring Vendor Besari, -Total pekerja 3orang -Progres 25%		
	Monitoring Vendor SDB di kitchen cretya lite (untuk freon yg di gunakan milik engineering)		

Vilas Harum

Bali

23/01/2026 friday	Monitoring Vendor di atap bar kopi bekerja 3 orang dan masih dlm pemasangan triplek		 realme C75 23 Januari 2026 pukul 22:48
25/01/2026 Sunday	Monitoring vendor di Ganesha Bekerja 7 orang Saat ini sedang melakukan pengecoran selop pondasi		 realme C75 25 Januari 2026 pukul 09:53
	Monitoring vendor pengecatan di Cretya Lite Extension		 OPPO A96 little boy 2026.01.26 21:41

Mas Harum

Bali

28/01/2026 Wednesday	Monitoring Vendor pemasangan railing di pathway bwh dj booth bekerja 2 orang		 realme C75 28 Januari 2026 pukul 19:14
30/01/2026 Friday	Vendor SDB melakukan pengecekan oven di pastry Permasalahan oven, pilot susah untuk ste bay disaan pagi hari ketika pilot masih dingin, saat hidupkan kenop harus di pompa dulu lalu dibuka dan di tahan sambil nyalahin pilotnya sampai benar" panas dan menyalah,, baru kenop di lepas secara perlahan,, jika masih blm bisa ste bay ulangi lagi brarti pilot belum benar" panas,, Untuk penyebabnya ada 2 yaitu 1. termo couple harus di ganti dgn yg asli (yg saat ini digunakan bukan yg asli) 2. Gas Valve nya perlu di ganti Untuk saat ini kondisi pilot sudah panas jadi saat pengetesan pilot sangat mudah untuk ste bay.		 realme C75 30 Januari 2026 pukul 14:16

Clas Harum
Bali

Pictures of Departmental Training Monthly

Departmental	Images
02/01/2026 Eng. Agenda : Materi 1 “refreshment cara pemasangan gas LPG di kitchen production” oleh spv engineering di kitchen production	 

09/01/2026

Eng. Agenda : Materi 2 “Cara pengecekan genset sebelum warming up” oleh SPV Engineering di Ruang Genset







19/01/2026

Eng. Agenda : Materi 3 “Operasional
PUTR Panel” oleh Chief Engineering di
Ruang Genset



23/01/2026

Eng. Agenda : Materi 4 “Preventif Maintenance” oleh Chief Engineering di office engineering



Engineering work order done

FB Product : 8
FB Service : 31
Activity & Concierge : 20
House keeping : 6
GSA : 5
Security : 3
Guide Comission : 5
HR & Sales Marketing : 7

Engineering work order Pending

FB Product : 11
FB Service : 82
Activity & Concierge : 33
House keeping : 13
GSA : 5
Security : 5
Guide Comission : 2
HR & Sales Marketing : 1

Engineering office	
Eng store	