




Hornby railway collection










Contact pxe.geek+hornby@gmail.com









Hi Res pictures available at [Hornby](#) collection

[RAILWAYANA](#) - a collection of various Hornby OO gauge trains and accessories, including an [operating](#)









Went under the hammer October 1st 2025 for 40 GBP.


Item	Description	Condition	Pictures	Comments
R758	BR Hymek Diesel Hydraulic Locomotive	Excellent		
R923	BR Intercity Buffet Car	Excellent		
R726	BR Intercity Brake 2nd Coach	Excellent		No box

R355G	Industrial Locomotive 27	Poor	  	Cosmetic damage - one footplate missing, signs of glue on another, and on chimney. No box
R15	BR United Dairies Milk Tankwagon	Poor	  	Cosmetic damage to tank retaining bracket. No box
R243	BR Mineral wagon	Excellent	  	No box

				
R16 218	BR Brake Wagon	Excellent	  	No box
R14	BR Insulated Fish Van	Excellent	  	No box
R576	Single Track Tunnel	Excellent		No box

				
R001	Wayside Halt	Good	 	Some cosmetic damage on platform
R192	Goods Depot	Good	 	Partially assembled
R629	Level Crossing	Good	 	
R145	Modern Signal Box "Ipswich"	Excellent	 	Ipswich label slightly peeling, but chimney intact

R201	Signal Kit	Excellent	 	
R405	Colour Light Signal	Unknown		No box.
R404	Operating Ore Wagon set	Excellent	 	Complete
R361 and other	Various Track pieces and other extras	Various	 	
R638	Roll of Track underlay	Extremely Poor		Probably unusable. I don't know why I still

				have it....