<u>Teardown Toyota Prius G9060-47190</u> ref 220103 <u>Click Here for Additional Photos</u>



Repair Notes:

Looks like the power transformer contacts have pulled out of the case.

Initial Inspection - Does not power up, Ground pin missing on AC plug, Open case,

NOTE: screws missing outside and inside, Remove AC Cord and J1772 cord. Remove

electronics, Reconnect AC Cord, CAUTION: the J1772

cord is polarized but can be installed improperly.













Failure Notes:

EVSE Charger Make, Model - Toyota 120v 12 Amp G9060-47190

EVSE Failure Symptom - Dropped now won't turn on, no lights and ground prong broke

Vehicle Make, Model & Year - 2013 prius plug-in

EVSE AC Power Connection - NEMA 5-15P - 120V